

# INSTRUCTION MANUAL

## GHD-20A

### Geared Head Drill (415V)

### 31.5mm Drilling Capacity with Automatic Feed



D134

# OPERATION      MANUAL

1 of 20

## Contents

1. Outline Drawing
2. Main Technical Specifications And Data
3. Main Applications And Features
4. Several Usage Regulations
5. Main Structure
6. Transmission System
7. Lubrication
8. Electric System
9. Lifting And Installation
10. Operation And Adjustment
11. Accessories

\*This Document Is A General Purpose Instruction, Some Differences Between Drawings And The Specific Machines Are Permitted.

## OPERATION

## MANUAL

2 of 20

## 1. Outline Drawing




Figure 1

## OPERATION MANUAL

3 of 20

## 2. Main Specifications

No	Technical Specifications and Data		Unit	Z5025B	Z5025-1B	Z5025-3B
2.1	Maximum Drilling Diameter ( $\sigma_B=500-600\text{mpa}$ )		mm	25(1)		
2.2	Maximum Travel of Spindle		mm(in)	140( $5\frac{1}{2}$ )		
2.3	Spindle Taper Hole			Morse No.3		
2.4	Distance Between the Center of Spindle and the Surface of the Vertical Column		mm(in)	315( $12\frac{3}{8}$ )		225( $8\frac{7}{8}$ )
2.5	Maximum Distance Between the Spindle Nose and the Surface of Working Table		mm(in)	660(26)	620( $24\frac{1}{2}$ )	600( $23\frac{5}{8}$ )
2.6	Maximum Distance Between the Spindle Nose and the Base Surface		mm(in)	1200( $47\frac{1}{4}$ )		1075( $42\frac{5}{16}$ )
2.7	Maximum Travel of the Supporting Block of the Working Table		mm(in)	480( $18\frac{7}{8}$ )	390( $15\frac{3}{8}$ )	412( $16\frac{1}{4}$ )
2.8	Maximum Travel of Spindle Box		mm(in)	240( $9\frac{7}{16}$ )		
2.9	Speeds of Spindle	50Hz	r/min	100, 205, 345, 440, 690, 885, 1450, 2900		
		60Hz		120, 245, 415, 530, 830, 1060, 1740, 3480		
2.10	Spindle Speed Variations			8		
2.11	Spindle Feed Variations			3		
2.12	Feed Rate of Spindle		mm/r	0.08, 0.16, 0.24		
2.13	Dimensions of the Working Table (L * W)		mm(in)	315 X 415 ( $12\frac{3}{8}$ )X( $16\frac{3}{8}$ )	$\phi 390/\phi 440$ ( $\phi 15\frac{3}{8}$ )( $\phi 17\frac{3}{8}$ )	275 X 315 ( $10\frac{13}{16}$ )X( $12\frac{7}{16}$ )
2.14	Dimensions of the Base Surface		mm(in)	475 X 400 ( $18\frac{11}{16}$ ) X ( $15\frac{3}{4}$ )		305 X 297 (12) X ( $11\frac{11}{16}$ )
2.15	Double-Speed 3-Phase Motor	Type		As 802/4		
		Power	Kw	0.75/0.90		
		Speed	r/mm	50Hz: 1400/2800; 60Hz: 1680/3360		
2.16	Overall Dimensions (L * W * H)		mm(in)	785 X 560 X 1820 (31 X 22 X $71\frac{5}{8}$ )		640 X 470 X 1670 (25 X $18\frac{1}{2}$ X $66\frac{5}{8}$ )
2.17	Net Weight		kg	465	290	295



### 3. Main Applications and Features

This machine tool is mainly applicable for enlarging, reaming, boring, countersinking and chamfering etc.

The gear transmission system has been applied, which results in the compact structure and high rigidity to meet the needs of strong force cutting operation.

The double-speed motor is applied in the transmission, leading a wide speed range. Feed motion can be realized by either manual or mechanical, with the advantage of quick, easy and safe operation.

Spindle box can be moved up and down and can be rotated 360° around the vertical column, so does the working table. the working table of Z5025B, Z5025-3B can be tilted  $\pm 45^\circ$ .

Up/down movement of spindle box and working table is by worm gear mechanism which is light to operate.

Drilling depth is controlled by a distance adjustment mechanism in addition to a auto-retract function.

Some gears in speed changing box are made of MC nylon to decrease noises.

Auto-reset function is provided to spindle sleeve.

### 4. Several Usage Regulations

- 1) Carefully read this user manual before start the machine.
- 2) Wearing gloves is not allowed when operate the machine. Contacting the spindle and tools by hands or other thing is strictly forbidden when it is running.
- 3) The machine has no short-circuit protection, the user is required to connect a 6A(rated Amper) protection switch. Earth protection must be well done in inlet circuit.
- 4) Strictly follow the lubrication requirements as noted.
- 5) When tapping, automatic feed is not allowed in order to avoid damaging machine.
- 6) Carefully clean the anti-rust grease before start machine, operate from low to high speed smoothly to check for the abnormal phenomena.
- 7) Whenever a failure happens, call the qualified person to repair it.

# OPERATION MANUAL

## 5. Main Structure

Main structure and parts(Fig.2-Fig.9)

- |                                       |                                |
|---------------------------------------|--------------------------------|
| 1) bottom base                        | 45) bearing 80103              |
| 2) spring washer                      | 46) shaft                      |
| 3) hex nut                            | 47) worm gear Z18              |
| 4) hose connector                     | 48) gear Z25                   |
| 5) cover plate                        | 49) gear Z39                   |
| 6) round head screw                   | 50) position key set           |
| 7) vertical column                    | 51) bearing 80103              |
| 8) small shaft                        | 52) speed changing lever       |
| 9) worm gear                          | 53) worm shaft                 |
| 10) worm shaft                        | 54) bearing 80102              |
| 11) gear rack                         | 55) gear Z34                   |
| 12) spindle box fasten mechanism      | 56) gear Z17                   |
| 13) spindle box up/down mechanism     | 57) gear Z22                   |
| 14) lift gear rack                    | 58) bearing 80102              |
| 15) vertical column                   | 59) bearing 8102               |
| 16) flexible metal pipe               | 60) gear Z31                   |
| 17) eye screw                         | 61) coil spring                |
| 18) speed changing box                | 62) up/down gear shaft         |
| 19) spindle box                       | 63) worm Z39                   |
| 20) drill retract handle              | 64) left clutch                |
| 21) working table                     | 65) clutch handle base         |
| 22) handle                            | 66) worm shaft                 |
| 23) press block                       | 67) gear                       |
| 24) turning shaft                     | 68) gear rack                  |
| 25) bracket                           | 69) fasten handle              |
| 26) sliding box                       | 70) feed changing wheel handle |
| 27) speed changing combination switch | 71) shaft                      |
| 28) start/stop switch                 | 72) shaft II                   |
| 29) motor                             | 73) shaft III                  |
| 30) spindle speed changing handle     | 74) gear Z33                   |
| 31) panel                             | 75) gear Z34                   |
| 32) feed handle                       | 76) gear Z51                   |
| 33) feed depth adjustment             | 77) gear Z68                   |
| 34) bearing D1000906                  | 78) connector                  |
| 35) round nut                         | 79) inner gear sheet           |
| 36) gear Z28                          | 80) gear Z42                   |
| 37) clutch gear Z49                   | 81) bearing 3056203            |
| 38) clutch                            | 82) gear Z42                   |
| 39) bearing 80103                     | 83) gear Z16                   |
| 40) worm shaft                        | 84) bearing 80203              |
| 41) limiter base                      | 85) gear Z16                   |
| 42) spindle                           | 86) shaft I                    |
| 43) bearing D2007107                  | 87) shaft pin                  |
| 44) spindle sleeve                    | 88) pin                        |
|                                       | 89) arm                        |

## OPERATION MANUAL

Page 2




Figure 3

Figure 2

## OPERATION

## MANUAL

7 of 20




Figure 4

## OPERATION

## MANUAL

8 of 20




Figure 5




Figure 6




Figure 7

## OPERATION

## MANUAL

10 of 20




Figure 8




Figure 9

## OPERATION MANUAL

1 of 20

## 6. Transmission System

### 1) The spindle rotate(Fig.8)

Through motor to shaft I 86. Through gear 83, 77 or 82, 80 to shaft II. Through gear 85, 76 or gear 75, 74 to shaft III. Through integral key to spindle. the motor has double-speed, through changing the transmission gear, the spindle will rotate in 8 different speeds.

### 2) Spindle feed motion.

The spindle feed motion can be controlled manually or mechanically, through gear 36, 37, clutch 38, flat key to worm shaft 40 (Fig.4), worm gear 47, shaft 46 (Fig.5), through operating the feed changing gear handle 70 (Fig.7), drive speed changing lever 52, to gear 48, 60 or 55, 57 or 49, 56, then to worm gear shaft 53 (Fig.5) to worm gear 63, left clutch 65, clutch handle base 65, through flat key to up/down gear shaft 62 (Fig.6), through gear, gear rack transmission, to make the spindle sleeve and spindle make the mechanical feed motion. Turning the feed handle 32 (Fig.2) separate the clutch handle base 65 from the left clutch 61, then the manual feed motion can be realized.

### 3) The up/down and rotary of the spindle box(Fig.7)

It is controlled by hand, loose the fasten handle 69, the spindle box can rotate around the vertical column. Through worm transmission to gear 67, gear 68, the spindle box will move up or down.

### 4) The motion of working table (Fig.2)

It is controlled by hand. the supporting block of working table can be moved up or down through worm 10, worm gear 9, gear rack 11.

## 7. Lubrication

The transmission gear of the speed changing box, spindle bearing and the transmission gear of the feed box uses precision machine tool grease No.2. Change it every year.  
the spindle box up/down handle and the up/down gear shaft should be oiled every shift by No. 30 oil.

## 8. Electric system

The circuit diagram is shown as Fig.11. the electric installation diagram is shown as Fig.12. the electric connection is shown as Fig.13.

The machine uses 3 phase, exchange power supply. It can be supplied according to user requirement. the machine has no short-circuit protection, the user is required to connect a 6A protection switch. Earth protection must be well down.

The double-speed motor rotates at 1400/2800 r/min for 50HZ and 1680/3360 r/min for 60HZ. the motor power is 550/750w. the two speeds are selected by SA switch. the reverse direction can also be selected. the start or stop is controlled by electromagnetism switch QS.

## 9. Lifting and installation

All locking handles must be locked before lift. (Fig.14)

The calculation of base edge depends on the maximum diameter which the working table turns 360° around the vertical column.

Figure 9 is the minimum dimension, you can adjust its height according to your request.

When installing the machine, bury the foot screw in a cement foundation according to the position of base holes, after the cement has condensed completely, place the machine on the cement foundation, adjust it to the demand of Go item on the inspection certificate with horizontal meter. the screw the foot screw steadily and evenly.



## OPERATION

## MANUAL

2 of 20




Figure 10 Location of Lubrication

## OPERATION MANUAL

13 of 20




Figure 11 Circuit diagram

SA Connection(" + "means connected)

NO	LW6-4/F525	NO	L-speed				H-speed			
			1L ccw	o	1R cw	o	2R cw	o	2L ccw	
(1)	W	1W1	(2)	+		+				
(3)	W	2W1	(4)					+		+
(5)		1U1	(6)	+		+				
(7)	1W1	1U1	(8)					+		+
(9)		1V1	(10)	+		+				
(11)	1W1	1V1	(12)					+		+
(13)		2V1	(14)					+		+
(15)		2U1	(16)					+		+
(17)	V		(18)			+		+		
(19)	V		(20)	+						+
(21)	U		(22)			+		+		
(23)	U		(24)	+						+

## OPERATION MANUAL

14 of 20




Figure 12 Installation diagram for electrics



## OPERATION

## MANUAL

16 of 20




Figure 14 Location of Lifting

## OPERATION MANUAL

17 of 20




Figure 15 Installation of foundation

## OPERATION      MANUAL

801 21

### 10. Operation and adjustment

When the spindle manual feed motion, first turning limiter base 41 (Fig.4) 180° . touch to the spindle box , then rotating feed handle 10 (Fig.16), the spindle will move up or down along with the sleeve 44 (Fig.4). When It automatic feed motion. Note make separate the limiter base 41 from the spindle box. Swing the feed handle 32(Fig2). separate the clutch handle base 65 from the left clutch 64 after the automatic feed operation, the sleeve will be reset by the coil spring 61. (Fig.6).

Remove the speed changing box, loosen the anti-motion washer to adjust the round nut 35(Fig.4), then the clearance of the spindle bearing can be adjusted. Please note that if the clearance is too small, the spindle will overheat and the other troubles may happen.

The locking of the spindle box and the supporting block of the working table can be adjusted by the hex nut 11. Loosen the cover nut first, adjust the hex nut to the proper position, then fasten the cover nut.

The above parts have been property adjusted before shipping. Unqualified person is not allowed to make these adjustments.

List of the Parts of Operation (Fig16)

No.	Name	No.	Name
1	Lock Screw	9	Feed handle of spindle
2	Up/down Handle of Supporting block	10	Feed Changing Handle
3	Intermediate sleeve with taper	11	Locking Screws and Nuts
4	Start/Stop Switch of the Motor	12	Locking Handle of Supporting Block
5	Up/down Handle of Spindle Box	13	Locking Handle of Working Table
6	Speed Changing Combination Switch	14	Tool Retracting Handle
7	Speed Changing Handle of the Spindle	15	Working Table
8	Speed Changing Handle of the Spindle	16	Supporting Block

Before starting the motor (Fig. 16), rotate the speed changing switch 6 to the required position ("2R" for high speed, "1R" for low speed, "2L" for high speed and reverse direction, "1L" for low speed and reverse direction). then press the button "1"(green) of the switch 4, the machine begins to work. Press "0" button (red) for stop the machine. When the spindle is rotating reverse, first, stop the machine. then rotate the speed changing combination switch 6. Wait until the motor stop completely, press the start switch.

The speed selection is realized through operating the spindle speed changing handle 7, and the feed rate selection through the feed changing wheel handle 10. Note that the speed only can be changed when the machine has stopped to avoid damages to the gears and the clutches.

When loosen the lock handle 69 (Fig.7), the spindle box can turn 360° around the vertical column 15 (Fig.2). the spindle box can move up or down and lock at any position by operating the up/down handle 5 . (Fig.16). the working table can move up or down by loosening the lock handle 12, rotating the handle 2. the working table support block can turn around the vertical column by loosening handle 13. the working table can turn by loosening the lock nut 1 the working table can be tilted  $\pm 45^\circ$ .



## OPERATION

## MANUAL

19 of 20




Figure 16



## OPERATION MANUAL

20 of 20

**11. Accessories:**

Name	Specification	Quantity	Remark
Three-jaw Drill Chuck	1—13 mm	1	
Taper Sleeve	3/2	1	
Taper Sleeve	3/1	1	
Drill Chuck Holder	ZF01	1	
Wedge for Taper Shank Tool	ZF02	1	

**12. Safety Cover Equipment**

The safety cover equipment is available as requirement .

The organic glass cover can protect the operator effectively. It can move up and down for covering different work-pieces.

MACHINERYHOUSE