

INSTRUCTION MANUAL

AL-1440 Centre Lathe (415V) 356 x 1000mm Turning Capacity - 40mm Bore



L244



Established 1930

Distributors of new & used workshop Equipment

L240 L242 AL1000C /AL1000D 9/18 SPEED

1340E/1440E LATHE

17-07-2007

CE

OPERATION MANUAL

&

PARTS LISTS

FOR


1340E/1440E

PRECISION HIGH

SPEED LATHE

IMPORTANT

BEFORE OPERATING THE MACHINE PLEASE READ CAREFULLY-
OPERATION INSTRUCTIONS PAGES 4~36 IN THE MANUAL.





INDEX

| | |
|--|-------|
| * SPECIFICATIONS AND ACCESSORIES----- | 3 |
| * GENERAL LAYOUT OF LATHE----- | 4 |
| * UNCRATING CLEANING LIFTING THE MACHINE----- | 5 |
| * CLEANING LIFTING----- | 6 |
| * INSTALLING----- | 7 |
| * LATHE ALIGNMENT----- | 8 |
| * LEVELING----- | 9 |
| * TRANSPORTATION INSTALLATION----- | 10 |
| * FOUNDATION DIAGRAM----- | 11 |
| * CHUCKS AND CHUCK MOUNTING----- | 12 |
| * TAPER TURNING ATTACHMENT----- | 13 |
| * LATHE CONTROL----- | 14 |
| * MAIN MOTOR CONTROLS, FOOT BRAKE----- | 15 |
| * CONTROL PANEL----- | 16 |
| * APRON CONTROLS, CROSS-SLIDE AND TOP SLIDE----- | 17 |
| * SLIDE WAYS ATTENTION, CROSS-SLIDE NUT----- | 18 |
| * TAILSTOCK----- | 19 |
| * ADJUSTMENT OF SLIPPING CLUTCH----- | 20 |
| * SPINDLE BEARING ADJUSTMENT----- | 20 |
| * THREADS AND FEEDS----- | 21 |
| * LUBRICATION CHART----- | 22 |
| * LUBRICATION CHECKS----- | 23 |
| * LUBRICATION CHECKS----- | 24 |
| * LUBRICATION----- | 25 |
| * "CE" CHARACTERISTICS----- | 26 |
| * "CE" NORMS ELECTRIC COMPONENTS----- | 27 |
| * "CE" NORMS WIRING CIRCUIT DIAGRAM----- | 28 |
| * "CE" NORMS ELECTRIC COMPONENTS POSITION----- | 29 |
| * WIRING DIAGRAM (1 PHASE)----- | 30 |
| * ELECTRIC COMPONENTS POSITION----- | 31 |
| * WIRING DIAGRAM (3 PHASE)----- | 32 |
| * ELECTRIC COMPONENTS POSITION----- | 33-36 |
| * PARTS LIST----- | 37-71 |
| * ELECTRIC EQUIPMENTS----- | 72 |
| * NOTES----- | 73 |
| * TROUBLE SHOOTING----- | 74 |
| * TOLERANCE PERMISSIBLE DIAGRAM----- | 75-77 |

SPECIFICATIONS AND ACCESSORIES

MODEL: LD-1340E(330mmx1000mm)
LD-1440E(360mmx1000mm)



SPECIFICATIONS:

| DESCRIPTION | METRIC SYSTEM | | INCH SYSTEM | |
|----------------------------|-------------------|------------|---------------------------------|---------|
| MODEL | 300 × 1000 | 360 × 1000 | 1340 | 1440 |
| SWING OVER BED | 330 | 360 | 13" | 14" |
| SWING OVER CROSS SLIDE | 195 | 225 | 7-5/8" | 8-3/4" |
| DISTANCE BETWEEN CENTERS | 1000 | | 40 | |
| SWING OVER GAP | 490 | 520 | 19-1/4" | 20-3/4" |
| WIDTH OF BED | 190 | | 7-9/16 | |
| NUMBERED OF SPINDLE SPEEDS | 9 | | | |
| RANGE OF SPINDLE SPEEDS | 80-2000R.P.M. | | | |
| HOLE THROUGH SPINDLE | 40mm | | 1-1/2" | |
| SPINDLE NOSE | D1-4 Camlock | | | |
| TAPER OF SPINDLE BORE | M.T.No.5 | | | |
| TAILSTOCK QUILL TAPER | M.T.No.3 | | | |
| TAILSTOCK QUILL TRAVEL | 110mm | | 4 ³ / ₈ " | |
| CROSS SLIDE TRAVEL | 175mm | | 6 ⁷ / ₈ " | |
| COMPOUND REST TRAVEL | 100mm | | 4" | |
| METRIC THREADS | (30)0.4-7.0MM | | (30)0.4-7.0MM | |
| INCH THREADS | (32)4-56TPI | | (32)3-56TPI | |
| LONGITUDINAL FEEDS | 0.068-0.936mm/REV | | 0.0016"-0.03 /REV | |
| CROSS FEEDS | 0.034-0.468mm/REV | | 0.0008"-0.015 /REV | |
| MACHINE NET WEIGHT | 600 KG | 620 KG | 1320 Ib | 1364 Ib |
| GROSS WEIGHT | 700 KG | 720 KG | 1540 Ib | 1584 Ib |
| CRATE DIMENSION L×W×H | 1905×762×1473 | | 75"×30"×58" | |


STANDARD ACCESSORIES

- 2HP 1PH 3HP 3PH main drive motor
- Rapid foot brake
- 4-ways tool post
- 6" & 8" Backplate(D1-4)
- Thread dial
- Gap bed
- Centers, M.T.No.3
- Center sleeve, M.T.No.5 × 3
- Set of change gears
- Tool kit & box
- Complete electric control unit
- Dual dials
- Face plate 10"(250mm)
- Steady rest
- Follow rest
- Rear splash guard
- 1/8HP coolant pump

OPTIONAL ACCESSORIES

- 3-jaw scroll chuck 6"(150mm)
- 4-jaw independent chuck 8"(200mm)
- Quick change tool post
- Single tool post
- Taper turning attachment
- Carriage micro stop
- Live centers MT#3
- Work lamp
- Drill chuck 13mm(1/2")w/arbor
- Chuck guard
- 4-position carriage stop
- Milling Attachment

GENERAL LAYOUT OF LATHE



- | | |
|---------------------------|------------------------------------|
| 1. HEADSTOCK | 10. LEAD SCREW |
| 2. SPINDLE | 11. SPINDLE ROTATION CONTROL LEVER |
| 3. TOP SLIDE | 12. CHIP PAN |
| 4. SADDLE AND CROSS-SLIDE | 13. APRON |
| 5. SPLASH GUARD | 14. FOOTBRAKE |
| 6. TAILSTOCK | 15. RACK |
| 7. BED | 16. GEAR BOX |
| 8. MOUNTING FEET | 17. END COVER (GEAR TRAIN) |
| 9. FEED SHAFT | 18. FORWARD/REVERSE CONTROL SHAFT |
| | 19. CONNECTION PLATE |

UNCRATING THE MACHINE

UPON RECEIPT OF SHIPMENT, REMOVE CRATING CAREFULLY BUT DON'T REMOVE SKIDS UNTIL THE LATHE HAS BEEN MOVED TO THE APPROXIMATE PLACE SELECTED OR ITS ERECTION.

CLEANING THE MACHINE

DO NOT MOVE THE CARRIAGE OR TAILSTOCK ON THE BEDWAYS BEFORE CLEANING THOROUGHLY AND OILING THE WAYS. USE A GOOD CLEAN GREASE SOLVENT TO REMOVE SLUSHING COMPOUND AND DIRT ACCUMULATED IN TRANSIT. USE RAGS RATHER THAN WASTE TO ELIMINATE LINT. DO NOT USE AN AIR HOSE AS THIS WILL FORCE GRIT AND DIRT INTO IMPORTANT FUNCTIONING UNITS. USE A STIFF BRISTLE BRUSH TO GET INTO CORNERS AND TO CLEAN LEADSCREW THOROUGHLY.

WHEN THE MACHINE HAS BEEN CLEANED SATISFACTORILY, RUB CLEAN MACHINE OIL OVER ALL WAYS AND MAKE CERTAIN NO GRIT REMAINS. BEFORE MOVING THE CARRIAGE ON THE BED, REMOVE THE FILLER PLUG ON THE TOP OF THE CARRIAGE AND FILL THE APRON WITH THE PROPER OIL AS SPECIFIED IN THE LUBRICATION CHART. OIL CARRIAGE WAYS ON BED. THEN PROCEED WITH MOVING THE CARRIAGE TO BALANCE THE LOAD. ALSO CHECK THE END GEARING FOR PROPER MESHING OF GEARS.

LIFTING THE MACHINE

TO OBTAIN A BALANCED CONDITION BEFORE LIFTING, IT IS NECESSARY TO MOVE THE TAILSTOCK TO THE RIGHT-HAND END OF THE BED AND CLAMP IT THERE. RESURE TO CLEAN BED WAYS BEFORE MOVING CARRIAGE OR TAILSTOCK.


NOTE

MAKE CERTAIN THE LOAD IS ON BALANCE AND THAT THE SLING DOES NOT TOUCH THE LEADSCREW OR CONTROL ROD BEFORE LIFTING.

IF A CRANE IS USED IN LIFTING, EXERCISE CARE THAT NONE OF THE MECHANISM IS DAMAGED. CHAIN, WIRE CABLE OR ROPE MAY BE USED TO LIFT THE LATHE.

IF ROPES ARE USED, BE CERTAIN THAT THEY ARE STRONG ENOUGH TO SAFELY CARRY THE WEIGHT OF THE MACHINE. THE FINISHED SURFACES OF THE MACHINE MUST BE PROTECTED FROM CHAINS BY USING WOODEN BLOCKS.

AFTER YOU RECEIVED THE MACHINE, PLS CHECK IF THE PACKING CONTENTS ALL THE ACCESSORIES YOU ORDERED.



CLEANING

BEFORE OPERATION ANY CONTROLS, REMOVE THE ANTICORROSION COATING FROM ALL SLIDWAYS, AND THE END GEAR TRAIN, USING WHITE SPIRIT OR KEROSENE.

DO NOT USE CELLULOSE SOLVENTS FOR CLEANING AS THEY WILL DAMAGE THE PAINT FINISH.


OIL ALL BRIGHT MACHINED SURFACES IMMEDIATELY AFTER CLEANING USING MACHINE OIL OR SLIDWAY LUBRICANT, USE HEAVY OIL OR ON THE END GEAR.

LIFTING

USE THE BED-CLAMPING PLATE AND EYEBOLT TO SLING THE LATHE, POSITION THE SADDLE AND TAILSTOCK ALONG THE BED TO OBTAIN BALANCE.

RAISING AND LOWERING THE MACHINE SHOULD BE DONE CAREFULLY, ESPECIALLY WHEN YOU LOVER THE MACHINE, BE SURE NOT TO BUMP THE MACHINE AGAINST THE FLOOR.

* IMPORTANT: DO NOT USE SLINGS AROUND BED AS LEADSCREW AND FEED-SHAFT MAY BE BENT.




INSTALLING

LOCATED THE MACHINE ON A SOLID FOUNDATION, ALLOWING SUFFICIENT AREA ALL ROUND FOR EASY WORKING AND MAINTENANCE (SEE FOUNDATION PLAN). THE LATHE MAY BE USED FREE-STANDING OR BOLTED TO THE FOUNDATION.

FREE-STANDING: POSITION LATHE ON FOUNDATION AND ADJUST EACH OF THE SIX MOUNTING FEET TO TAKE EQUAL SHARE OF THE LOAD. THEN USING AN ENGINEERS PRECISION LEVEL ON THE BEDWAYS ADJUST THE FEET TO LEVEL UP MACHINE. PERIODICALLY CHECK BED LEVEL TO ENSURE CONTINUED LATHE ACCURACY.

FIXED INSTALLATION: POSITION LATHE OVER SIX BOLTS ($\frac{1}{2}$ IN. OR 12 mm. DIAM.) SET INTO THE FOUNDATION TO CORRESPOND WITH HOLES IN THE MOUNTING FEET. ACCURATELY LEVEL THE MACHINE, THEN TIGHTEN HOLD-DOWN BOLTS. RE-CHECK BED LEVEL.




LATHE ALIGNMENT

B. TAILSTOCK CHECK

USING A 12IN. (305MM.) GROUND STEEL BAR FITTED BETWEEN HEADSTOCK AND TAILSTOCK CENTERS, CHECK THE ALIGNMENT BY FITTING A DIAL-TEST INDICATOR TO THE TOPSLIDE AND TRAVERSING THE CENTER LINE OF THE BAR.

TO CORRECT ERROR RELEASE THE TAILSTOCK CLAMP LEVER AND ADJUST THE TWO SET-OVER SCREWS PROVIDED CONTINUE WITH CHECKING AND CORRECTION UNTIL THE ALIGNMENT IS PERFECT.



LEVELING

LEVELING THE LATHE

The lathe should be kept perfectly level at all times

Leveling Procedure

CLEAN THE BEDWAYS THOROUGHLY AND MAKE SURE THE BEDWAYS ARE DRY AFTER CLEANING, BACK OFF ALL LEVELING SCREWS SO THE BASE IS SITTING ON THE FLOOR. PLACE A 6" PRECISION MACHINIST SPIRIT LEVEL OVER A PARALLEL IF THE LEVEL USED HAS A V-BASE, NOW PLACE THE LEVEL WITH THE BASE ON THE FRONT FLAT WAY, IF THE BASE OF THE LEVEL IS FLAT, IT CAN THEN BE DIRECTLY PLACED ON THE FLAT WAY, PLACE THE LEVEL LENGTHWISE AT THE HEADSTOCK END AND LEVEL FOR A ZERO READING.

MOVE THE LEVEL TO THE TAILSTOCK END AND ADJUST THE OUTER END LEVELING SCREWS TO OBTAIN SAME READING AS ON THE HEADSTOCK END.

NOW PLACE THE LEVEL OVER A BRIDGE ACROSS AT THE HEADSTOCK END, TAKE A READING AND MOVE THE LEVEL TO THE TAILSTOCK END. THE READING AT THIS END MUST BE EXACTLY THE SAME AS THE OTHER END. NO TWIST IS PERMISSIBLE.

MAKE ADJUSTMENTS TO GET THE SAME READING AT BOTH ENDS.


IT WILL BE NECESSARY TO REPEAT THIS PROCEDURE SEVERAL TIMES, FOR MAKING NECESSARY ADJUSTMENTS, YOU WILL FIND THAT THE ADJUSTMENTS AT ONE END WILL AFFECT THE READING OF THE OTHER, AFTER THE END LEVELING SCREW ADJUSTMENTS ARE COMPLETE, TURN DOWN THE CENTER LEVELING SCREWS AT THE HEADSTOCK END UNTIL THEY REST UNDER SLIGHT TENSION. THE TENSION SHOULD BE SUCH THAT IT DOES NOT CHANGE THE LEVEL READING.

RECHECK LEVEL AT THIS TIME AND MAKE ONLY MINOR ADJUSTMENT, IF NECESSARY. AFTER THE MACHINE HAS BEEN PUT TO USE FOR A PERIOD OF TIME, CHECK LEVEL TO OBSERVE IF THE ORIGINAL CONDITION EXISTS, MAKE ADJUSTMENTS IF NECESSARY.

(MARK ONE END OF THE LEVEL WITH A ERASABLE MARKER SO THAT THE LEVEL POINTS IN THE SAME DIRECTION FOR EVERY READING.)

CARPENTER'S OR COMBINATION SQUARE LEVEL ARE NOT ACCURATE AND MUST NOT BE USED, SCHEDULE A PERIODIC LEVEL CHECK AS A PART OF YOUR MAINTENANCE SCHEDULE.

POSITIONING OF SPIRIT LEVELS



TRANSPORTATION/INSTALLATION

PREPARATION FOR USE *****


SELECTING LOCATION FOR MACHINE

FOR BEST RESULTS FROM ANY LATHE, IT IS IMPORTANT THAT THE ZONE SELECTED FOR ITS ERECTION BE WELL-LIGHTED, AS DRY AS POSSIBLE, AND AS FREE AS POSSIBLE FROM VIBRATION.


THE MACHINE SHOULD BE LOCATED SO THAT ADEQUATE SPACE IS PROVIDED FOR UTILIZATION OF MAXIMUM RAUGES, AS WELL AS THE SPACE REQUIRED FOR MAKING ADJUSTMENTS. A MINIMUM OF 28 INCHES CLEARANCE SPACE SHOULD BE PROVIDED AT THE ENDS AND REAR OF THE LATHE AND AT LEAST 40 INCHES AT THE FRONT FOR THE OPERATOR.

FOUNDATION

A SPECIAL FOUNDATION IS NOT ESSENTIAL FOR THIS MACHINE. HOWEVER, IT IS ADVISABLE TO PLACE IT ON A SUBSTANTIAL FOUNDATION OF CONCRETE IF POSSIBLE. IF PLACED ON A WOODEN FLOOR, CARE SHOULD BE TAKEN TO SEE THAT IT IS ADEQUATELY SUPPORTED AND FREE FROM VIBRATION. IF THE MACHINE IS TO BE PLACED ON AN UPPER FLOOR, LOCATE IT DIRECTLY OVER A SUPPORTING BEAM OR GRINDER TO REDUCE ANY VIBRATION GENERATED BY NEARBY MACHINES



FUNDATION DIAGRAM



CHUCKS AND CHUCK MOUNTING


WHEN FITTING CHUCKS OR FACE PLATES, FIRST ENSURE THAT SPINDLE AND CHUCK TAPERS ARE PERFECTLY CLEAN AND THAT ALL CAMS LOCK IN THE CORRECT POSITIONS, SEE FIG. IT MAY BE NECESSARY WHEN MOUNTING A NEW CHUCK TO RE-SET THE CAMLOCK STUDS(A). TO DO THIS, REMOVE THE CAPHEAD LOCKING SCREWS(B) AND SET EACH STUD SO THAT THE SCRIBED RING(C) IS FLUSH WITH THE REAR FACE OF THE CHUCK-WITH THE SLOT LINING UP WITH THE LOCKING SCREW HOLE.

NOW MOUNT THE CHUCK OR FACEPLATE ON THE SPANDLE NOSE AND TIGHTEN THE SIX CAMS IN TURN. WHEN FULLY TIGHTENED, THE CAM LOCK LINE ON EACH CAM SHOULD BE BETWEEN THE TWO V MARKS ON THE SPINDLE NOSE.

IF ANY OF THE CAMS DO NOT TIGHTEN FULLY WITHIN THESE LIMIT MARKS, REMOVE THE CHUCK OR FACEPLATE AND RE-ADJUST THE STUD AS INDICATED IN THE ILLUSTRATION. FIT AND TIGHTEN THE LOCKING SCREW(B) AT EACH STUD BEFORE REMOUNTING THE CHUCK FOR WORK. A REFERENCE MARK SHOULD BE MADE ON EACH CORRECTLY FITTED CHUCK OR FACEPLATE TO COINCIDE WITH THE REFERENCE MARK SCRIBED ON THE SPINDLE NOSE.



THIS WILL ASSIST SUBSEQUENT REMOUNTING: DO NOT INTERCHANGE CHUCKS OR FACE PLATES BETWEEN LATHES WITHOUT CHECKING FOR CORRECT CAM LOCKING BEFOREHAND.

***** IMPORTANT: TAKE CAREFUL NOTE OF SPEED LIMITATION WHEN USING FACEPLATE; 10 INCH FACEPLATES SHOULD NOT BE RUN AT SPEEDS GREATER THAN 1000 REV/MIN. AND 12INCH FACEPLATES AT NOT MORE THAN 750 REV/MIN.**




INSTRUCTIONS FOR ASSEMBLING TAPER ATTACHMENT ON LATHES:

1. LOOSEN CROSS FEED NUT "E".
2. FIT TAPER ATTACHMENT ON THE CARRIAGE AND LOCK IT BY SCREWS.
3. ADJUST SLIDE "A" PARALLELY TO BED BY 0.015MM PER 150MM THROUGH A DIAL METER.
4. INSTALL BOLT "F" ON BLOCK "D".
5. MOUNT THE PART "B" ON CROSS SLIDE AND LOCK IT BY SCREWS.
6. LOCK THE PART "B" ON BLOCK "D" BY NUT.
7. SET BRACKET "C" ON BED WAY.



LATHE CONTROL




1. SPINDLE SPEED SELECTOR
2. SPEED SELECT LEVER
3. SLIDE CROSS FEED HANDWHEEL
4. TOOLPOST CLAMPING LEVER
5. TOP SLIDE HANDWHEEL
6. SADDLE CLAMPING LEVER
7. TAILSTOCK BARREL CLAMPING LEVER
8. TAILSTOCK CLAMPING LEVER
9. TAILSTOCK HANDWHEEL
10. POSITIVE-REVERSE LEVER
11. FEED AND THREAD SELECTORS
12. FOOT BRAKE
13. APRON LONGITUDINAL FEED HANDWHEEL
14. AUTOMATIC FEED LEVER
15. THREAD CUTTING HALF-NUT LEVER
16. SPINDLE ROTATION (FORWARD AND REVERSE)

* MAIN MOTOR ROTATION:

SELECTED BY THE LEVER CONTROLS (THE LOCATED ON RIGHT HAND SIDE OF THE APRON) MOVE LEVER OUT AND UPWARD TO ENGAGE FORWARD ROTATION OF SPINDLE. OR OUT AND DOWN TO ENGAGE REVERSE ROTATION. OR RETURNED TO THE CENTRAL POSITION TO DISENGAGE DRIVE.

* FOOT BRAKE:


A FOOT PEDAL BETWEEN PLINTHS OPERATES THE SPINDLE BRAKE.



*** * * CAUTION * * ***

1. During the machine run in high speed, please do not change rapidly the controlling lever from forwarding to reversing or from reversing to forwarding to ensure machine in safety and prevent the motor from damage.
2. An additional micro switch is fitted for the foot brake. Upon the foot brake is operated, the magnetic switch on the spindle motor will be cut off automatically.
3. If an emergency stop is need, then pedal only the foot brake to cut the power off from the spindle motor. Also, the brake lining will be operated to stop the spindle rapidly.
4. For a regular operation stop, put only the brake starting lever in the middle position to cut the magnetic switch off and stop the machine.

CONTROL PANEL



*** CAUTION: DO NOT SHIFT GEARS WHEN THE SPINDLE IS RUNNING.

1. THE EMERGENCY STOP: PRESS THE RED MUSHROOM-HEAD BUTTON TO STOP THE MAIN MOTOR AND COOLANT PUMP.
2. INCHING BUTTON: PRESS THE GREEN BUTTON TO MOVE SPINDLE SLIGHTLY, IT WILL MARK SPINDLE SPEED SELECTION VERY EASY, (WHILE THE SPINDLE ROTATION LEVER IS SET IN THE NEUTRAL POSITION).
3. PILOT LAMP.
4. COOLANT PUMP ON/OFF SWITCH.

CROSS SLIDE AND TOP SLIDE

A SOLID TOP-SLIDE IS FITTED AS STANDARD TO THE CROSS-SLIDE, CARRIED ON A ROTATABLE BASE THE CROSS-SLIDE IS MARKED 45° $-0-45^{\circ}$ DEG. FOR ACCURATE INDEXING.


HANDWHEEL DIALS ARE GRADUATED IN INCH OR METRIC DIVISION TO SUIT THE OPERATING SCREW AND NUT FITTED.

THE CROSS-SLIDE CAN BE POWER OPERATED BY PULLED DOWNWARD THE AUTOMATIC FEED LEVER AT HALF SLIDING FEED PER SPINDLE REVOLUTION OR IF CAN BE HAND-OPERATED USING THE LARGE-DIAMETER DIAL GRADUATED IN EITHER INCH OR METRIC DIVISIONS TO SUIT THE OPERATING SCREW AND NUT FITTED.

APRON CONTROLS

IN ADDITION TO HANDWHEEL TRAVERSES, THE CARRIAGE CAN BE POWER-OPERATED THROUGH CONTROLS ON THE FRONT OF THE APRON, AUTOMATIC FEED LEVER (A) IF MOVE UPWARDS, CARRIAGE WOULD DO LONGITUDINAL-FEED OPERATION. IF MOVE LEVER (A) IN MIDDLE POSITION, IT WOULD DO MANUAL OPERATION. IF MOVE LEVER (A) DOWNWARDS, IT WOULD DO CROSS-FEED OPERATION.


LEVER (B) IS PRESSED DOWNWARD TO ENGAGE THE LEADSCREW NUT FOR SCREW CUTTING, TO AVOID UNDUE WEAR. RELEASE THE NUT EXCEPT WHEN SCREW CUTTING, AN INTERLOCK WITHIN THE APRON PREVENTS IN ADVERTENT ENGAGEMENT OF AUTOMATIC FEED LEVER (A) AND HALF NUT LEVER (B) AT THE SAME TIME.



SLIDE WAYS ATTENTION

TAPERED GIB STRIPS ARE FITTED TO SLIDEWAYS OF SADDLE CROSS-SLIDE AND TOP (COMPOUND) SLIDES SO THAT ANY SLACKNESS WHICH MAY DEVELOP CAN BE RECTIFIED.


ENSURE THAT SLIDEWAYS ARE THOROUGHLY CLEANED AND LUBRICATED BEFORE ATTEMPTING ADJUSTMENT. THEN RESET THE GIBS BY SLACKENING THE REAR GIB SCREW AND TIGHTENING THE FRONT SCREW, A LITTLE AT A TIME. CHECK CONSTANTLY FOR SMOOTH ACTION THROUGHOUT FULL SLIDE TRAVEL; AVOID OVERADJUSTMENT WHICH CAN RESULT IN INCREASED WEAR-RATE AND STIFF OR JERKY ACTION.



GIB ADJUSTERS

CROSS-SLIDE NUT


THIS IS ADJUSTABLE FOR ELIMINATION OF SLACKNESS WHICH MAY DEVELOP IN SERVICE. REDUCE BACKLASH BY THE CAP-HEAD SCREW REAR OF THE NUT, THEN MAKE ONLY SMALL ADJUSTMENT BY THE CAP-HEAD SCREW. BEFORE OPERATING THE CROSS-SLIDE SEVERAL TIMES BY HAND TO BE SURE OF SMOOTH OPERATION THROUGHOUT TRAVEL.



TAIL STOCK


CAN BE FREED MOVEMENT ALONG THE BED BY UNLOCKING THE CLAMP LEVER (A). THE TAILSTOCK BARREL IS LOCKED BY LEVER (B).

THE TAILSTOCK CAN BE SET-OVER FOR PRODUCTION OF SHALLOW TAPERS OR FOR RE-ALIGNMENT, RELEASE THE CLAMPING LEVER (A) AND ADJUST SCREW (S) AT EACH SIDE OF THE BASE TO MOVE TAILSTOCK LATERALLY ACROSS THE BASE. RETIGHTENING AND CHECKING AFTER ADJUSTMENT OF SET OVER.




ADJUSTMENT OF SLIPPING CLUTCH

APRON HAS AN OVERLOAD PROTECTION DEVICE BY MEANS OF SLIPPING CLUTCH. THIS ADJUSTMENT CAN BE ACCOMPLISHED BY ADJUSTING SCREW(S) BE SURE DO NOT ADJUST THIS SCREW SO FREQUENTLY BECAUSE SLIPPING CLUTCH DOES NOT WEAR SO MUCH EVEN FOR A LONG PERIOD OF USE.



SPINDLE BEARING ADJUSTMENT

WHEN WE FIND THE SPINDLE BEARINGS ARE TOO TIGHT OR LOOSE, OPEN THE HEAD-STOCK COVER (A) AND LOOSE THE SET SCREW (B) ON THE SPINDLE BEARING THRUST NUT (C) AND THEN ADJUST THE THRUST NUT BY LOOSING OR FASTENING IT. THE PROPER ADJUSTMENT IS FINISHED BY FASTENING THE SET SCREW AGAIN.







THREADS AND FEEDS











****FOR INCH GEAR BOX****

CHECK THE CHART FOR THE DESIRED FEED AND TURN THE CHANGE LEVER.(W,X,Y,Z)AND (P,Q,R,I.T.)AND TURN THE SELECTOR KNOB (A,B)(C,D) IN THE GEAR BOX. TO THE OBTAIN THE DESIRED SPEED SHOWN ON THE RIGHT CHART.

***** CAUTION *****

DO NOT CHANGE GEARS AND FEEDS WHEN SPINDLE IN HIGHER SPEED RANGE.


|  | | PITCH | | | | | MM | | | |
|---|-------------|-------|-------|-------|-----|-------|-----|-------|------|--|
| | | T | U | S | U | S | R | U | R | |
|  | AD | 3.2 | 3.6 | 4.0 | 4.8 | 5.0 | 5.6 | 6.0 | 7.0 | |
| | BD | 1.6 | 1.8 | 2.0 | 2.4 | 2.5 | 2.8 | 3.0 | 3.5 | |
| | AC | 0.8 | 0.9 | 1.0 | 1.2 | 1.25 | 1.4 | 1.5 | 1.75 | |
| | BC | 0.4 | 0.45 | 0.5 | 0.6 | | 0.7 | 0.75 | | |
| | T.P.I. INCH | | | | | | | | | |
|  | U | S | T | U | T | T | T | T | | |
| | X | Y | X | X | X | X | X | X | | |
| | AD | 4 | 4 1/2 | 4 3/4 | 5 | 5 1/2 | 6 | 6 1/2 | 7 | |
| | BD | 8 | 9 | 9 1/2 | 10 | 11 | 12 | 13 | 14 | |
| | AC | 16 | 18 | 19 | 20 | 22 | 24 | 26 | 28 | |
|  | BC | 32 | 36 | 38 | 40 | 44 | 48 | 52 | 56 | |
| | FEED | | | | | | | | | |
| | MM | | | | | | | | | |
| | X | Y | Z | | | | | | | |
| | PAD | 0.554 | 0.752 | 0.936 | | | | | | |
| PBD | 0.272 | 0.376 | 0.468 | | | | | | | |
| PAC | 0.136 | 0.188 | 0.234 | | | | | | | |
| PBC | 0.068 | 0.094 | 0.117 | | | | | | | |

| | | | | | | | | | | |
|---|--|-------------|--------|--------|--------|---|---|---|-------|---|
|  | | T.P.I. INCH | | | | | | | | |
|  | | P | P | Q | T | R | R | Q | R | |
| | | X | X | X | Z | X | X | Z | W | |
| | | 60 | 65 | 60 | 60 | 57 | 60 | 60 | 60 | |
| | | AD | 3 | 3 1/4 | 4 | 4 1/4 | 4 3/4 | 5 | 5 1/2 | 7 |
| | | BD | 6 | 6 1/2 | 8 | 9 | 9 1/2 | 10 | 11 | 14 |
| | | AC | 12 | 13 | 16 | 18 | 19 | 20 | 22 | 28 |
| | | BC | 24 | 26 | 32 | 36 | 38 | 40 | 44 | 56 |
|  | | PITCH MM | | | | | | | | |
|  | | 28 | 28 | 42 | 35 | 49 | 30 | 49 | 36 | |
| | | R | Q | R | Q | R | Q | Q | Q | |
| | | W | W | W | W | X | W | X | | |
| | | AD | 3.2 | 4.0 | 4.8 | 5.0 | 5.6 | 6.0 | 7.0 | 7.2 |
| | | BD | 1.6 | 2.0 | 2.4 | 2.5 | 2.8 | 3.0 | 3.5 | 3.6 |
| | | AC | 0.8 | 1.0 | 1.2 | 1.25 | 1.4 | 1.5 | 1.75 | 1.8 |
| | | BC | 0.4 | 0.5 | 0.6 | | 0.7 | 0.75 | | 0.9 |
|  | | FEED | | | | | | | | |
|  | | MM | | | |  |  |  | |  |
| | | I | I | I | I | | | | | |
| | | W | X | Y | Z | | | | | |
| | | AD | 0.021 | 0.0295 | 0.0638 | 0.0226 | | | | |
| | | BD | 0.0105 | 0.0148 | 0.0184 | 0.0113 | | | | |
| | | AC | 0.0053 | 0.0072 | 0.0092 | 0.0056 | | | | |
| | | BC | 0.0026 | 0.0036 | 0.0046 | 0.0028 | | | | |


****FOR METRIC GEAR BOX****

CHECK THE CHART FOR THE DESIRED FEED AND TURN THE CHANGE LEVER (X,Y,Z) AND (R,S,T,P,U) TURN THE SELECTOR KNOB (A,B) (C,D) IN THE GEAR BOX. TO THE OBTAIN THE DESIRED SPEED SHOWN ON THE LEFT CHART.

LUBRICATION CHART



| | | |
|-----------------|-----------|---------------|
| | | |
| TWICE PER DAY 2 | OIL DAILY | CHECK DAILY 1 |



CAUTIONS ON OILING

THE FOLLOWING CAUTIONS ARE VERY IMPORTANT TO BE FOLLOWED WHEN OILING.

- (1) USE ONLY SPECIFIED OIL OR GREASE WITH SPECIFIED QUANTITY. TO USE OIL OR GREASE OTHER THAN SPECIFIED AND TOO MUCH AMOUNT OF OIL OR GREASE MAY ADVERSELY AFFECT THE PERFORMANCE OF THE MACHINE.
- (2) CLEAN THE SLIDE WAYS, OIL FILLER HOLES, OIL TANK, ETC. BEFORE POURING OIL AND USE CARE NOT TO POLLUTE OIL WHEN POURING OIL.
- (3) WHEN POURING OIL, PLACE A FILTER OVER OIL FILLER HOLE TO ELIMINATE DUST AND CONTAMINATOR. IF FILTER IS NOT AVAILABLE, USE A WIRE NET OF 150 MESH OR FINER.
- (4) SUCCESSIVELY USE THE IDENTICAL OIL OR GREASE. NOTE THAT THE USE OF OIL HAVING DIFFERENT PROPERTIES MIGHT DEGRADE THE OIL.
- (5) EVEN WHEN NEW OIL IS DRAINED, AND USED AGAIN FOR REASSEMBLING, REPLACEMENT OF PART OR ANY OTHER REASON, BE SURE TO FILTER THE OIL WHEN POURING THE OIL AGAIN.
- (6) DO NOT FULLY USE OIL OF OIL CAN, BUT LEAVE A SMALL QUANTITY OF OIL IN THE CAN. THIS CAUTIONS SHOULD BE FOLLOWED TO ELIMINATE MOISTURE AND SEDIMENT FROM OIL.

LUBRICATION CHECKS

A. HEADSTOCK

HEADSTOCK BEARING AND GEARS ARE SPLASH LUBRICATED. ENSURE THAT OIL LEVEL IS KEPT BETWEEN H-L LEVEL MARK ON THE SIGHT GLASS IN THE CHUCK-FACE OF HEADSTOCK. AFTER LONG TIME OF OPERATION, WHEN THE HEADSTOCK LUBRICATION OIL BECOMES UNCLEAR IT SHOULD BE DRAINED OUT TO REFILL FRESH LUBRICATION OIL.

TO CHANGE OIL IN HEADSTOCK, SET APRON CONTROL LEVER TO CENTRAL POSITION AND STOP THE MAIN MOTOR. UNSCREW THE DRAIN PLUG BESIDE HEADSTOCK, THEN THE OIL TANK CAN BE EASILY DRAINED OUT FOR CHANGING OIL. A FILLER PLUG IS FITTED BESIDE THE LEFT END OF THE HEADSTOCK ACCESSIBLE AFTER REMOVAL OF THE END GUARD.

B. GEARBOX

THE GEARBOX IS SPLASH-LUBRICATED FROM ON INTERNAL RESERVOIR OF OIL. CHECK THE OIL LEVEL CONSTANTLY TO THE MARK ON THE OIL SIGHT WINDOW AT THE FRONT OF GEARBOX. A WEEKLY CHECK IS RECOMMENDED, WITH THE OIL CHANGED EVERY SEMI ANNUAL. FILL OIL THROUGH A FILLER CAP IN THE TOP OF THE GEAR BOX. ENCLOSED BY THE END-GUARD. DRAIN FROM A DRAIN PLUG IN THE BOTTOM OF THE GEAR BOX.

C. APRON

APRON OILING SHOULD BE MADE THROUGH THE OIL INLET IN THE TOP OF THE SADDLE. BY REMOVING THE CAP OF THE OIL INLET THE OIL MUST BE ALWAYS KEPT WITH THE HORIZONTAL CENTER LINE OF THE OIL SIGHT AT THE FRONT OF THE APRON TO DRAIN THE PLUG AT THE LOWER OF APRON WHEN TAKING OFF THE OIL.

FILL APRON RESERVOIR THROUGH INLET TO LEVER THE SIGHT WINDOW WITH SHELL TONNA OIL 27 LUBRICANT.

D. OTHER PORTIONS


THERE ARE OIL INLETS IN CROSS SLIDE. COMPOUND REST, FEED SCREW SHAFT BEARING, AND BRACKET WHICH HOLDS ROD, LEAD SCREW AND TAILSTOCK, HAND OILING IS REQUIRED FROM TIME TO TIME.

*** ENSURE THAT THE SLIDEWAYS ARE THOROUGHLY CLEANED AND LUBRICATED BEFORE OPERATING THE LATHE.

LUBRICATION CHECKS

BEFORE OPERATING THE MACHINE MAKE THE FOLLOWING IMPORTANT CHECKS:

1. THAT THE HEADSTOCK IS FILLED TO LEVEL MARKED ON OIL SIGHT WINDOW WITH SHELL TELLUS OIL 27.
2. THAT THE GEARBOX FILLED TO LEVEL MARKED ON OIL SIGHT WINDOW WITH SHELL TELLUS OIL 27.
3. THAT THE CARRIAGE APRON IS FILLED TO LEVEL MARK ON OIL SIGHT WINDOW WITH SHELL TONNA 33.
4. IN ADDITION, APPLY AN OIL CAN TO THE POINTS SHOWN ON LUBRICATION DIAGRAM WHICH REQUIRE DAILY OILING, USE LIGHT MACHINE OIL OR WAY LUBRICANT.




LUBRICATION

IN ADDITION TO PUMP-FED LUBRICATION, OILER POINTS ARE PROVIDED FOR THE SADDLE, CROSS-SLIDE, CROSS-SLIDE NUT AND USING A STANDARD PUMP-TYPE CAN WITH LIGHT MACHINE OIL OR WAY LUBRICANT, SEE FIG.


ON THE TAILSTOCK, TAIL END OF LEADSCREW OILER POINTS ARE PROVIDED FOR DAILY ATTENTION FROM A STANDARD OIL CAN.

IT IS RECOMMENDED THAT ALL SLIDEWAYS, THE LEADSCREW AND FEED SHAFT ARE CLEANED OFF (A BRISTLE PAINT BRUSH IS USEFUL FOR THIS) AND LIGHTLY OILED AFTER EACH PERIOD OF WORK.


NOTE: USE OF INCORRECT GRADED OF CAN CAUSE DAMAGE.




"CE" CHARACTERISTICS:




A CHUCK GUARD WITH LIMIT SWITCH IS FITTED. (The machine is stopped automatically when the chuck guard is lifted up.)




TOOL SLIDE GUARD IS MOUNTED ON THE SADDLE TO ENSURE OPERATION SAFELY.




LEAD SCREW IS INSTALLED WITH MOVABLE COVER PROTECTED TO ENSURE OPERATION SAFELY.



END COVER IS CONNECTED WITH A LIMIT SWITCH ON THE SIDE OF HEADSTOCK. (The machine is stopped automatically when the end cover is opened.)




A MAIN SWITCH IS MOUNTED ON THE DOOR OF ELECTRIC BOX TO CONTROL ELECTRIC SUPPLY.



ELECTRIC BOX CONTAINS "CE" STANDARD COMPONENTS.


LD-1340E,LD-1440E MOTOR FOR "CE" NORMS ELECTRIC COMPONENTS
FOR 3HP 50HZ 24V CONTROL.

| NO. | DESCRIPTION | BRAND | CODE | SPEC. | REMARK |
|-----|-------------------|-------------|-------------|-----------------|----------|
| 1 | MAGNETIC SWITCH | TAIAN | CN-11 | 380V/4KW | K1,K2,K5 |
| 2 | MAGNETIC SWITCH | TAIAN | CN-11 | 380V/4KW | K3 |
| 3 | MAGNETIC SWITCH | TAIAN | CN-11 | 380V/4KW | K4 |
| 4 | OVERLOAD ROLAY | TAIAN | RHN-10M | 0.3-0.464A/380V | F3 |
| 5 | OVERLOAD ROLAY | TAIAN | RHN-10M | 4-6A/380V | F2 |
| 6 | POWER TRANSFORMER | ZIENTE | TC130VA/24V | | TR 1 |
| 7 | DOOR SWITCH | AB | 194L-A16 | | Q 1 |
| 8 | FUSE HOLDER | GEC ALSTHOM | 10 x38 | 32A/660V | MF |
| | | FMC 101 | | | |
| 9 | FUSE | GEC ALSTHOM | 10 x38 | 32A/660V | F5,F4 |
| | | FMC 101 | | | |
| 10 | TERMINAL | AB | 1492-W4 | 800V/15A | |
| 11 | LIMIT SWITCH | OMRON | D4BS-25FC | | |
| | | TE | XCK-P591 | | |
| 12 | LIMIT SWITCH | OMRON | D4D-1532N | | |
| | | TE | XCK-P102 | | |
| 13 | FOR/REV SWITCH | HIGHLY | Z15G/1306 | | |
| 14 | PUMP SWITCH | TE | ZB2-BE101 | | |
| 15 | PUSH BUTTON | TE | ZB2-BE101 | | |
| 16 | PILOT LIGHT | TE | ZB2-BE101 | | |
| 17 | EMERGENCY SWITCH | TE | ZB2-BE102 | | |



"CE" NORMS WIRING CIRCUIT DIAGRAM

"CE" MARKING ELECTRIC COMPONENTS POSITION



T1: CONTROL CIRCUIT TRANSFORMER.

K2: FOR MAIN MOTOR REVERSE AC MAGNETIC CONTACTOR COIL.

K1: FOR MAIN MOTOR FORWARD AC MAGNETIC CONTACTOR COIL.

K3: FOR PUMP MOTOR AC MAGNETIC CONTACTOR COIL.


K4: AC MAGNETIC CONTACTOR COIL.

F2,F3: THERMAL OVERLOAD RELAY.

F4,F5: CIRCUIT TRANSFORMER WITH FUSE 32A/660V.


Q1: DOOR SWITCH.


MF: MAIN POWER FUSE.




LS4 : LIMIT SWITCH FOR MAIN MOTOR FORWARD

WIRING DIAGRAM (3 PHASE)






"CSA" NORMS WIRING CIRCUIT DIAMGRAM
MODEL: LD-1340E, 1440E.



| | |
|-----------------|----------------------------|
| LIANG DEL LATHE | |
| Title | LATHE CONTROL CIRCUIT |
| Size | Document Number |
| A3 | RE |
| Date: | FEBRUARY 26, 2001 15:56:01 |



F3: MAIN FUSE.

F5.F4: FUSE.

Q1: DOOR SWITCH.

T1; CONTROL CIRCUIT TRANSFORMER.

K1: FOR MAIN MOTOR FORWARD AC MAGNETIC CONTACTOR COIL.

K2: FOR MAIN MOTOR REVERES AC MAGNETIC CONTACTOR COIL.

K3: FOR PUMP MOTOR AC MAGNETIC CONTACTOR COIL.

K4: AC MAGNETIC CONTACTOR COIL.

F1.F2: THERMAL OVERLOAD RELAY.


TB: TERMINAL BLOCK.

PART LIST

MODEL:LD-1340E


LD-1440E

LD-1440V




HEADSTOCK (CASTING & CONTROLS)

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|-------------------------------|------|---------|
| 1 | 2101 | HEADSTOCK CASTING | 1 | |
| 2 | 2143 | HEADSTOCK COVER | 1 | |
| 3 | 2121 | SHAFT | 1 | |
| 4 | 2122 | GEAR (M2X32T) | 1 | |
| 5 | 2123 | WASHER | 1 | |
| 6 | 2124 | SHAFT | 1 | |
| 7 | 2125 | GEAR (M2X38T) | 1 | |
| 8 | 2126 | HANDLE | 1 | |
| 9 | 2127 | GEAR SHIFT FORK | 1 | |
| 10 | 2136 | SHAFT | 2 | |
| 11 | 2137 | FORK ARMS | 2 | |
| 12 | 2138 | GEAR SHIFT FORK | 2 | |
| 13 | 2139 | COLLAR | 2 | |
| 14 | 2141 | HANDLE | 2 | |
| 15 | 2142 | CONTROL LEVER | 2 | |
| 16 | 2194 | OIL RING | 2 | |
| 17 | 2193 | PIN (5mmx32mm) | 2 | |
| 18 | 2184 | CAP SCREW (6mmx25mm) | 6 | |
| 19 | 2195 | PLUG (3/8 G.P.) | 1 | |
| 20 | 2144 | OIL SIGHT(29mm) | 1 | |
| 21 | 2181 | OIL RING(P20) | 1 | |
| 22 | 2148 | SNAP RING (S18) | 1 | |
| 23 | 2178 | WASHER | 1 | |
| 24 | 2180 | BEARING (6004) | 2 | |
| 25 | 2145 | KEY(5mmx18mm) | 1 | |
| 26 | 2146 | OIL RING (P12) | 1 | |
| 27 | 2188 | SNAP RING (S40) | 1 | |
| 28 | 2185 | INDICATOR PLATE | 3 | |
| 29 | 2191 | OIL RING (P12) | 2 | |
| 30 | 2189 | CAP SCREW (6mmx16mm) | 4 | |
| 31 | 2192 | SPRING PIN (5mmx40mm) | 2 | |
| 32 | 2186 | STEEL BALL SPRING & SET SCREW | 2 | 8mmx6mm |
| 33 | 2190 | PVC KNOB | 2 | |
| 34 | 2183 | PLUG (5/8") | 1 | |
| 35 | 2196 | DATA PLATE | 1 | |
| 36 | 2197 | SCREW (3/16"x3/8") | 4 | |




HEADSTOCK (SPINDLE & GEARS)

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|---------------------------------|------|---------|
| 10 | 2112 | SHAFT | 1 | |
| 11 | 2116 | GEAR (M2x19T) | 1 | |
| 12 | 2117 | GEAR (M2x60T) | 1 | |
| 13 | 2118 | GEAR (M2x52T) | 1 | |
| 14 | 2119 | BORE PLUG | 1 | |
| 15 | 2120 | COVER | 1 | |
| 16 | 2113 | GEAR (M2x30T) | 1 | |
| 17 | 2114 | GEAR (M2x50T) | 1 | |
| 18 | 2115 | GEAR (M2x40T) | 1 | |
| 19 | 2135 | COVER (BACK) | 1 | |
| 20 | 2134 | LOCK NUT | 1 | |
| 21 | 2133 | GEAR (M2x38T) | 1 | |
| 22 | 2132 | GEAR (M2x80T) | 1 | |
| 23 | 2131 | GEAR (M2x39T) | 1 | |
| 24 | 2130 | GEAR (M2x48T) | 1 | |
| 25 | 2128 | COVER (FRONT) | 1 | |
| 26 | 2129 | MAIN SPINDLE | 1 | |
| 38 | 2162 | SNAP RING (S25) | 1 | |
| 39 | 2163 | KEY (6mmx22mm) | 2 | |
| 37 | 2158 | BEARING (#6204) | 2 | |
| 40 | 2164 | SNAP RING (S35) | 1 | |
| 41 | 2165 | SNAP RING (R47) | 1 | |
| 42 | 2166 | OIL RING (P39.4) | 1 | |
| 43 | 2159 | SCREW (CAP 6mmx16mm) | 6 | |
| 44 | 2180 | GASKET | 1 | |
| 46 | 2161 | SNAP RING (S45) | 1 | |
| 48 | 2167 | GASKET | 1 | |
| 49 | 2147 | SCREW (CAP 6mmx25mm) | 2 | |
| 50 | 2168 | BEARING (#30211) | 1 | |
| 51 | 2169 | SNAP RING (S55) | 1 | |
| 52 | 2170 | SNAP RING (S58) | 1 | |
| 53 | 2171 | BEARING (#30212) | 1 | |
| 54 | 2172 | GASKET | 1 | |
| 55 | 2173 | SCREW (CAP 6mmx25mm) | 3 | |
| 56 | 2174 | KEY (6mmx15mm) | 1 | |
| 57 | 2175 | KEY (7mmx75mm) | 1 | |
| 58 | 2176 | CAM D1-4 | 3 | |
| 59 | 2182 | STUD | 3 | |
| 60 | 2177 | DETENT PLUNGER,SPRING AND SCREW | 3 | |



MAIN MOTOR AND BRAKE SHOES ASSY


| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|-----------------------|------|---------|
| 1 | 2111 | NUT (M2xP1.5mm) | 1 | |
| 2 | 2110 | V-BELT PULLY | 1 | |
| 3 | 2107 | STUD | 1 | |
| 4 | 2108 | SHAFT LEVER | 1 | |
| 5 | 2106 | COVER | 1 | |
| 6 | 2102 | SHAFT | 1 | |
| 7 | 2103 | GEAR (M2x39T) | 1 | |
| 8 | 2104 | GEAR (M2x18T) | 1 | |
| 9 | 2105 | GEAR (M2x29T) | 1 | |
| 18 | 2618 | MOTOR PLATE | 1 | |
| 19 | 2653 | MOTOR PULLEY | 1 | |
| 27 | 2149 | WASHER | 1 | |
| 28 | 2109 | BRAKE SHOES ASSY | 1 | |
| 29 | 2140 | SPRING | 2 | |
| 30 | 2151 | SNAP RING | 1 | |
| 31 | 2153 | CAP SCREW | 1 | |
| 32 | 2152 | SCREW (CAP 6mmx25mm) | 3 | |
| 33 | 2179 | GASKET | 1 | |
| 34 | 2155 | BEARING (#6205) | 1 | |
| 35 | 2156 | KEY (6mmx30mm) | 1 | |
| 36 | 2157 | KEY (6mmx80mm) | 1 | |
| 37 | 2158 | BEARING (#6204) | 1 | |
| 49 | 2619 | WASHER | 2 | |
| 50 | 2631 | SCREW (CAP 10mmx35mm) | 2 | |
| 51 | 2652 | MAIN MOTOR | 1 | |
| 52 | 2656 | WASHER | 4 | |
| 53 | 2657 | SCREW (CAP 8mmx30mm) | 4 | |
| 54 | 2659 | KEY (8mmx45mm) | 1 | |
| 55 | 2655 | SCREW (SET 10mmx20mm) | 1 | |
| 56 | 2654 | V-BELT | 2 | |



GEARBOX (CASTING & CONTROLS)

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|---------------------------------|------|---------|
| 1 | 2224 | COVER | 1 | |
| 2 | 2225 | HANDLE | 1 | |
| 3 | 2226 | SHAFT | 1 | |
| 4 | 2227 | HANDLE | 1 | |
| 5 | 2228 | SHIFT LEVER | 1 | |
| 6 | 2229 | SHIFT LEVER | 1 | |
| 7 | 2230 | SHIFT FORK | 3 | |
| 8 | 2231 | LEVER | 2 | |
| 9 | 2233 | HANDLE | 1 | |
| 10 | 2234 | SHIFT FORK | 1 | |
| 11 | 2241 | SCREW (3/16x3/8 IN) | 6 | |
| 12 | 2248 | SCREW (CAP 6mmx30mm) | 6 | |
| 13 | 2247 | SET SCREW SPRING AND STEEL BALL | 2 | |
| 14 | 2251 | KEY (5mmx10mm) | 1 | |
| 15 | 2244 | OIL RING (P24) | 1 | |
| 16 | 2243 | SPRING PIN (5mmx40mm) | 1 | |
| 17 | 2242 | SPRING PIN (5mmx30mm) | 1 | |
| 18 | 2250 | PVC KNOB | 2 | |
| 19 | 2253 | SET SCREW SPRING AND STEEL BALL | 2 | |
| 20 | 2246 | OIL RING (P34) | 2 | |
| 21 | 2245 | SNAP RING (S40) | 2 | |
| 22 | 2249 | INDEXING PLATE | 2 | |
| 23 | 2252 | OIL SIGHT (29mm) | 1 | |
| 24 | 2254 | GASKET | 1 | |
| 25 | 2232 | HANDLE | 1 | |
| 26 | 2240 | DATA PLATE | 1 | |


INCH TYPE



GEARBOX (GEAR & SHAFT) INCH TYPE


| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|-------------------------------|------|---------|
| 1 | 2201 | GEAR BOX CASTING | 1 | |
| 2 | 2204 | COVER | 1 | |
| 3 | 2202 | SHAFT | 1 | |
| 4 | 2203 | GEAR (M2x27TX18T) | 1 | |
| 5 | 2236 | GEAR (14Px27Tx30T)(M2.25x21T) | 1 | |
| 6 | 2205 | COVER | 1 | |
| 7 | 2206 | SHAFT | 1 | |
| 8 | 2218 | COVER | 1 | |
| 9 | 2208 | SHAFT | 1 | |
| 10 | 2209 | GEAR (M2x27T) | 1 | |
| 11 | 2210 | GEAR (M2x18T) | 1 | |
| 12 | 2211 | GEAR (M2x36T) | 1 | |
| 13 | 2217 | GEAR (M2.25x28T) | 1 | |
| 14 | 2216 | GEAR (14Px30T) | 1 | |
| 15 | 2215 | GEAR (14Px24T) | 1 | |
| 16 | 2237 | GEAR (14Px33T) | 1 | |
| 17 | 2212 | SPACER | 1 | |
| 18 | 2213 | SHAFT | 1 | |
| 19 | 2222 | COVER | 1 | |
| 20 | 2220 | GEAR (M2x36Tx18T) | 1 | |
| 21 | 2235 | GEAR (14Px24Tx30T)(M2.25x20T) | 1 | |
| 22 | 2219 | SHAFT | 1 | |
| 23 | 2223 | COVER | 1 | |
| 24 | 2272 | PIN (5mmx28mm) | 2 | |
| 25 | 2273 | CAP SCREW (8mmx30mm) | 3 | |
| 26 | 2256 | OIL SEAL (22x35x7) | 1 | |
| 27 | 2255 | CAP SCREW (6mmx20mm) | 6 | |
| 28 | 2267 | KEY (5mmx18mm) | 1 | |
| 29 | 2258 | KEY (6mmx40mm) | 1 | |
| 30 | 2259 | BEARING (6004) | 3 | |
| 31 | 2260 | SNAP RING (S20) | 1 | |
| 32 | 2261 | BEARING (6003) | 5 | |
| 33 | 2262 | NUT | 1 | |
| 34 | 2269 | WASHER | 1 | |
| 35 | 2263 | THRUST (51105) | 3 | |
| 37 | 2275 | CAP SCREW (6mmx20mm) | 9 | |
| 38 | 2268 | KEY (6mmx55mm) | 1 | |
| 39 | 2266 | SNAP RING (S25) | 1 | |
| 40 | 2264 | KEY (5mmx60mm) | 1 | |
| 41 | 2265 | KEY (5mmx12mm) | 1 | |
| 44 | 2274 | SNAP RING (S22) | 2 | |
| 45 | 2276 | OILER (5/16 IN) | 1 | |
| 46 | 2277 | SCREW (CAP 8mmx10mm) | 1 | |

METRIC TYPE







GEARBOX (GEAR & SHAFT) METRIC TYPE

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|-----------------------------------|------|---------|
| 1 | 2201 | GEAR BOX CASTING | 1 | |
| 2 | 2204 | COVER | 1 | |
| 3 | 2202 | SHAFT | 1 | |
| 4 | 2203 | GEAR (M2x27TX18T) | 1 | |
| 47 | 2207 | GEAR (M2.25x20T)(14Px30T)(M2x25T) | 1 | |
| 6 | 2205 | COVER | 1 | |
| 7 | 2206 | SHAFT | 1 | |
| 8 | 2218 | COVER | 1 | |
| 9 | 2208 | SHAFT | 1 | |
| 10 | 2209 | GEAR (M2x27T) | 1 | |
| 11 | 2210 | GEAR (M2x18T) | 1 | |
| 12 | 2211 | GEAR (M2x36T) | 1 | |
| 13 | 2217 | GEAR (M2.25x28T) | 1 | |
| 14 | 2216 | GEAR (14Px30T) | 1 | |
| 15 | 2215 | GEAR (14Px24T) | 1 | |
| 48 | 2214 | GEAR (M2x30T) | 1 | |
| 17 | 2212 | SPACER | 1 | |
| 18 | 2213 | SHAFT | 1 | |
| 19 | 2222 | COVER | 1 | |
| 20 | 2220 | GEAR (M2x36Tx18T) | 1 | |
| 49 | 2221 | GEAR (M2.25x21T)(14Px30T) | 1 | |
| 22 | 2219 | SHAFT | 1 | |
| 23 | 2223 | COVER | 1 | |
| 24 | 2272 | PIN (5mmx28mm) | 2 | |
| 25 | 2273 | CAP SCREW (8mmx30mm) | 3 | |
| 26 | 2256 | OIL SEAL (22x35x7) | 1 | |
| 27 | 2255 | CAP SCREW (6mmx20mm) | 6 | |
| 28 | 2267 | KEY (5mmx18mm) | 1 | |
| 29 | 2258 | KEY (6mmx40mm) | 1 | |
| 30 | 2259 | BEARING (6004) | 3 | |
| 31 | 2260 | SNAP RING (S20) | 1 | |
| 32 | 2261 | BEARING (6003) | 5 | |
| 33 | 2262 | NUT | 1 | |
| 34 | 2269 | WASHER | 1 | |
| 35 | 2263 | THRUST (51105) | 3 | |
| 37 | 2275 | CAP SCREW (6mmx20mm) | 9 | |
| 38 | 2268 | KEY (6mmx55mm) | 1 | |
| 39 | 2266 | SNAP RING (S25) | 1 | |
| 40 | 2264 | KEY (5mmx60mm) | 1 | |
| 41 | 2265 | KEY (5mmx12mm) | 1 | |
| 44 | 2274 | SNAP RING (S22) | 2 | |
| 45 | 2276 | OILER (5/16 IN) | 1 | |
| 46 | 2277 | SCREW (CAP 8mmx10mm) | 1 | |



APRON (CASTING)


| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|---------------------------------|------|---------|
| 1 | 2301 | APRON CASTING | 1 | |
| 11 | 2316 | BRACKET | 1 | |
| 12 | 2317 | GEAR SHAFT (M1.5x16T) | 1 | |
| 13 | 2318 | LEVER | 2 | |
| 14 | 2362 | INDEXING PLATE | 1 | |
| 23 | 2309 | WORM | 1 | |
| 24 | 2310 | COLLAR | 2 | |
| 25 | 2325 | HALF NUT CLUTCH | 1 | |
| 26 | 2326 | GIB | 1 | |
| 27 | 2358 | OIL SIGHT (29mm) | 1 | |
| 28 | 2357 | CAP SCREW (8mmx10mm) | 1 | |
| 29 | 2355 | STEEL BALL SET SCREW AND SPRING | 1 | |
| 30 | 2354 | SET SCREW (6mmx10mm) | 3 | |
| 31 | 2356 | PLUG (5/8 IN) | 1 | |
| 32 | 2352 | SNAP RING (S 30) | 2 | |
| 33 | 2353 | CAP SCREW (6mmx20mm) | 2 | |
| 39 | 2363 | CAP SCREW (6mmx40mm) | 4 | |
| 40 | 2360 | CAP SCREW (8mmx25mm) | 1 | |
| 41 | 2361 | SCREW (3/16x3/8 IN) | 3 | |
| 42 | 2359 | PVC KNOB | 2 | |



APRON (GEAR & SHAFT)


| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|-----------------------|------|---------|
| 2 | 2302 | GEAR SHAFT(M2x12T) | 1 | |
| 3 | 2303 | KEEP ASSY | 1 | |
| 4 | 2304 | INDEX RING | 1 | |
| 5 | 2305 | HANDWHEEL | 1 | |
| 6 | 2306 | HANDLE | 1 | |
| 7 | 2307 | GEAR SHAFT (M1.5x13T) | 1 | |
| 8 | 2308 | GEAR (M2x50T) | 1 | |
| 9 | 2314 | SHAFT | 1 | |
| 10 | 2315 | GEAR(M2x22T)(M2x44T) | 1 | |
| 15 | 2311 | SHAFT | 1 | |
| 16 | 2312 | GEAR(M2x22T) | 1 | |
| 17 | 2313 | GEAR(M1.5x18T) | 1 | |
| 18 | 2319 | SHAFT | 1 | |
| 19 | 2320 | COLLAR | 1 | |
| 20 | 2321 | SHAFT | 1 | |
| 21 | 2322 | LEVER | 1 | |
| 22 | 2323 | HANDLE | 1 | |
| 34 | 2340 | CAP SCREW(6mmx16mm) | 3 | |
| 35 | 2341 | STEEL BALL AND SPRING | 1 | |
| 36 | 2342 | PIN (5mmx50mm) | 1 | |
| 37 | 2343 | PIN (5mmx30mm) | 2 | |
| 38 | 2344 | CIRCLIP (E12) | 1 | |
| 43 | 2348 | KEY (5mmx14mm) | 2 | |
| 44 | 2346 | SNAP RING (S14) | 2 | |
| 45 | 2351 | PIN (5mmx40mm) | 1 | |

INCH TYPE(LEADSCREW 4TPI)



| INDICATOR TABLE | | | | | |
|-----------------|------------|-------|-------|-------|-------|
| T.P.1 | SCALE | T.P.1 | SCALE | T.P.1 | SCALE |
| 4 | 1-8 | 12 | 1-8 | 38 | 1-8 |
| 4 1/2 | 1 1/2, 3/4 | 13 | 1-4 | 40 | |
| 4 3/4 | 1 | 14 | 1-8 | 44 | |
| 5 | 1-4 | 16 | | 48 | |
| 5 1/2 | 1 1/2, 3/4 | 18 | | 52 | |
| 6 | 1-8 | 19 | 1-4 | 56 | |
| 6 1/2 | 1 1/2, 3/4 | 20 | | 64 | |
| 7 | 1-4 | 22 | | 72 | |
| 8 | 1-8 | 24 | | 76 | |
| 9 | 1-4 | 26 | 1-8 | 80 | |
| 9 1/2 | 1 1/2, 3/4 | 28 | | 96 | |
| 10 | 1-8 | 32 | | 104 | |
| 11 | 1-4 | 36 | | 112 | |


METRIC TYPE(LEADSCREW PICH 4MM)



| INDICATOR TABLE | | | |
|-----------------|-------|------|---------|
| GEAR | PITCH | | SCALE |
| 18T | 0.45 | 0.9 | 1, 4 |
| | 0.3 | 0.6 | 13, 5 |
| | 0.25 | 0.75 | 1-6 |
| | 0.5 | 1.5 | |
| | 1 | 3 | |
| 20T | 1.25 | 60 | |
| | 2.5 | | 1, 4 |
| 21T | 1.75 | 70 | 1, 3, 5 |
| | 3.5 | | |


THREADING INDICATOR

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|----------------------------------|------|---------|
| 1 | 2327 | THREAD BODY INDICATOR | 1 | |
| 2 | 2328 | THREAD DIAL BODY (INCH TYPE) | 1 | |
| 3 | 2329 | GEAR (M2x16T) | 1 | |
| 4 | 2366 | FLAT WASHER | 1 | |
| 5 | 2365 | CAP SCREW (6mmx12mm) | 1 | |
| 6 | 2364 | CAP SCREW (6mmx45mm) | 1 | |
| 7 | 2336 | THREAD CHART PLATE (IN TYPE) | 1 | |
| 8 | 2328-1 | THREAD DIAL BODY (METRIC TYPE) | 1 | |
| 9 | 2330 | GEAR (M1.25x18T) | 1 | |
| 10 | 2331 | GEAR (M1.25x20T) | 1 | |
| 11 | 2332 | GEAR (M1.25x21T) | 1 | |
| 12 | 2366 | FLAT WASHER | 1 | |
| 13 | 2365 | CAP SCREW (6mmx12mm) | 1 | |
| 14 | 2337 | THREAD CHART PLATE (METRIC TYPE) | 1 | |




SADDLE & CROSS-SLIDE

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|---------------------------|------|---------|
| 1 | 2401 | SADDLE CASTING | 1 | |
| 2 | 2402 | CROSS-SLIDE | 1 | |
| 3 | 2403 | CLAMP REAR | 1 | |
| 4 | 2404 | GIB | 1 | |
| 5 | 2405 | CLAMP FRONT | 2 | |
| 6 | 2406 | CAP SCREW (7/16x2-1/2 IN) | 1 | |
| 7 | 2407 | WASHER | 1 | |
| 8 | 2408 | GIB | 1 | |
| 9 | 2409 | GIB SCREW | 2 | |
| 10 | 2410 | COLLAR | 1 | |
| 11 | 2419 | NUT | 2 | |
| 12 | 2411 | GEAR (M2x13T) | 1 | |
| 13 | 2412 | SCREW | 1 | |
| 14 | 2413 | NUT | 1 | |
| 15 | 2414 | KEEP ASSY | 1 | |
| 16 | 2415 | INDEX RING | 1 | |
| 17 | 2417 | HANDWHEEL | 1 | |
| 18 | 2416 | PLUG | 1 | |
| 19 | 2418 | HANDLE | 1 | |
| 20 | 2439 | WIPER | 2 | |
| 21 | 2440 | WIPER | 2 | |
| 22 | 2465 | DIAL | 1 | |
| 23 | 2450 | OILER (1/4 IN) | 5 | |
| 24 | 2454 | CAP SCREW (8mmx20mm) | 3 | |
| 25 | 2453 | SCREW AND NUT | 1 | |
| 26 | 2451 | CAP SCREW (8mmx16mm) | 2 | |
| 27 | 2452 | SCREW (3/16x1/2 IN) | 8 | |
| 28 | 2466 | CAP SCREW | 2 | |
| 29 | 2467 | PIN | 2 | |
| 30 | 2462 | CAP SCREW (8mmx20mm) | 1 | |
| 31 | 2461 | CAP SCREW (8mmx20mm) | 1 | |
| 32 | 2460 | KEY (5mmx12mm) | 1 | |
| 33 | 2459 | PIN (5mmx22mm) | 1 | |
| 34 | 2457 | THRUST (2902) | 2 | |
| 35 | 2458 | CAP SCREW (6mmx25mm) | 2 | |
| 36 | 2468 | NAIL (2mm) | 2 | |
| 37 | 2456 | STEEL BALL AND SPRING | 1 | |
| 38 | 2455 | SCREW (12mmx12mm) | 1 | |
| 39 | 2464 | WASHER | 1 | |
| 40 | 2463 | CAP SCREW (6mmx12mm) | 2 | |




TOP-SLIDE

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|------------------------|------|---------|
| 1 | 2420 | SWIVEL SLIDE | 1 | |
| 2 | 2421 | TOP-SLIDE (T-SLOT) | 1 | |
| 3 | 2422 | GIB | 1 | |
| 4 | 2423 | SCREW | 2 | |
| 5 | 2424 | NUT | 1 | |
| 6 | 2425 | LEAD SCREW | 1 | |
| 7 | 2426 | BRACKET | 1 | |
| 8 | 2427 | INDEXING RING | 1 | |
| 9 | 2428 | HANDWHEEL | 1 | |
| 10 | 2429 | GRIP (LONG) | 1 | |
| 11 | 2430 | GRIP (SHORT) | 1 | |
| 12 | 2416 | NUT | 1 | |
| 13 | 2442 | SPRING | 1 | |
| 14 | 2431 | PIN | 1 | |
| 15 | 2432 | BOLT | 1 | |
| 16 | 2441 | T-SLOT NUT | 1 | |
| 17 | 2433 | 4-WAY TOOL POST | 1 | |
| 18 | 2434 | WASHER | 1 | |
| 19 | 2435 | HUB | 1 | |
| 20 | 2436 | LEVER | 1 | |
| 21 | 2437 | PVC KNOB | 1 | |
| 22 | 2438 | SCREW (3/8 IN) | 8 | |
| 23 | 2443 | DIAL | 1 | |
| 24 | 2463 | SET SCREW (6mmx12mm) | 1 | |
| 25 | 2444 | NUT | 1 | |
| 26 | 2462 | CAP SCREW (8mmx16mm) | 2 | |
| 27 | 2445 | STEEL BALL | 1 | |
| 28 | 2469 | SCREW | 1 | |
| 29 | 2450 | OIL CAP (1/4 IN) | 3 | |
| 30 | 2464 | KEY (4mmx10mm) | 1 | |
| 31 | 2465 | THRUST BEARING (51101) | 2 | |
| 32 | 2466 | CAP SCREW (6mmx25mm) | 2 | |
| 33 | 2446 | NAIL (2mm) | 2 | |
| 34 | 2467 | STEEL BALL & SPRING | 1 | |
| 35 | 2455 | SCREW (12mmx12mm) | 1 | |
| 36 | 2468 | SET SCREW | 2 | |



TAILSTOCK


| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|----------------------|------|---------|
| 1 | 2501 | TAILSTOCK CASTING | 1 | |
| 2 | 2502 | ATILSTOCK BASE | 1 | |
| 3 | 2503 | TAILSTOCK BARREL | 1 | |
| 4 | 2504 | NUT | 1 | |
| 5 | 2505 | FEED SCREW | 1 | |
| 6 | 2506 | BRACKET | 1 | |
| 7 | 2507 | DIAL | 1 | |
| 8 | 2508 | HANDWHEEL | 1 | |
| 9 | 2509 | NUT | 1 | |
| 10 | 2510 | HANDLE | 1 | |
| 11 | 2511 | NUT | 1 | |
| 12 | 2512 | SHAFT | 1 | |
| 13 | 2513 | LEVER | 1 | |
| 14 | 2514 | COLLAR | 1 | |
| 15 | 2515 | CAM SHAFT | 1 | |
| 16 | 2516 | CLAMP STUD | 1 | |
| 17 | 2517 | CLAMP | 1 | |
| 18 | 2518 | CLAMP HANDLE LEVER | 1 | |
| 19 | 2519 | STEEL BALL & SPRING | 1 | |
| 20 | 2520 | SET SCREW (8mmx30mm) | 2 | |
| 21 | 2521 | SET SCREW (8mmx30mm) | 2 | |
| 22 | 2522 | WASHER | 1 | |
| 23 | 2523 | NUT | 1 | |
| 24 | 2524 | CAP SCREW (8mmx20mm) | 1 | |
| 25 | 2525 | NUT | 1 | |
| 26 | 2526 | PVC KNOB | 2 | |
| 27 | 2528 | KEY (5mmx12mm) | 1 | |
| 28 | 2529 | THRUST BEARING(2902) | 1 | |
| 29 | 2530 | CAP SCREW (6mmx20mm) | 3 | |
| 30 | 2531 | SCREW (12mmx12mm) | 1 | |
| 31 | 2527 | DIAL | 1 | |
| 32 | 2532 | SCREW(3/16"x3/8") | 2 | |
| 33 | 2533 | OIL CAP(1/4") | 1 | |




BED RACK LEAD SCREW AND SHAFTS

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|---------------------------------|------|---------|
| 1 | 2601 | BED | 1 | |
| 2 | 2602 | GAP | 1 | |
| 3 | 2603 | RACK | 1 | |
| 4 | 2604 | RACK | 1 | |
| 5 | 2605 | LEAD SCREW (4 T.P.I.)(4 MM) | 1 | |
| 6 | 2606 | SHAFT | 1 | |
| 7 | 2607 | FOR/REV CONTROL,THIRD-ROD SHAFT | 1 | |
| 8 | 2609 | COLLAR | 1 | |
| 9 | 2608 | COLLAR | 1 | |
| 10 | 2617 | END BRACKET | 1 | |
| 11 | 2611 | BUSH | 1 | |
| 12 | 2610 | BOX | 1 | |
| 13 | 2612 | BUSHING | 1 | |
| 14 | 2613 | BRACKET | 1 | |
| 15 | 2614 | BUSH | 1 | |
| 16 | 2615 | BUSH | 1 | |
| 17 | 2616 | LEVER | 1 | |
| 18 | 2630 | PVC KNOB | 1 | |
| 20 | 2634 | SCREW (CAP 1/2"x2") | 6 | |
| 21 | 2621 | WASHER | 6 | |
| 22 | 2622 | NUT | 6 | |
| 23 | 2623 | SCREW (CAP 10mmx40mm) | 2 | |
| 24 | 2624 | SCREW (CAP 10mmx35mm) | 2 | |
| 25 | 2632 | SCREW (CAP 10mmx35mm) | 4 | |
| 26 | 2633 | SCREW TAPER PIN | 2 | |
| 27 | 2627 | NUT | 2 | |
| 28 | 2636 | SCREW (CAP 6mmx20mm) | 6 | |
| 29 | 2635 | PIN (5mmx28mm) | 4 | |
| 30 | 2637 | SCREW (SET 8mmx12mm) | 1 | |
| 31 | 2638 | STEEL BALL AND SPRING | 2 | |
| 32 | 2639 | SCREW (SET 8mmx10mm) | 1 | |
| 33 | 2640 | THRUST (#51104) | 1 | |
| 34 | 2651 | SCREW (8mmx60mm) | 2 | |
| 35 | 2650 | PIN (5mmx50mm) | 2 | |
| 36 | 2658 | PLUG | 2 | |
| 37 | 2649 | OIL CUP (1/4") | 3 | |
| 38 | 2642 | SCREW (SET 8mmx10mm) | 1 | |
| 39 | 2641 | SCREW (CAP 6mmx16mm) | 2 | |
| 40 | 2628 | SCREW (SET 6mmx16mm) | 1 | |
| 41 | 2629 | PIN (5mmx28mm) | 1 | |
| 42 | 2643 | SPRING | 1 | |
| 43 | 2646 | PIN (5mmx28mm) | 1 | |
| 44 | 2644 | SCREW (CAP 6mmx20mm) | 2 | |
| 45 | 2645 | SCREW (CAP 6mmx10mm) | 1 | |
| 46 | 2648 | SCREW (SET 8mmx8mm) | 1 | |
| 47 | 2647 | NUT | 1 | |

CHUCK GUARD LIMIT SWITCH




CE COVER




CHUCK GUARD LIMIT SWITCH & CE COVER

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|---------------------------|------|---------|
| 1 | 2901 | COVER | 1 | |
| 2 | 2912 | CAP SCREW (8mmx20mm) | 2 | |
| 3 | 2913 | WASHER | 2 | |
| 4 | 2914 | ROD | 1 | |
| 5 | 2911 | SCREW (CAP 6mmx16mm) | 1 | |
| 6 | 2906 | SCREW (SET 8mmx20mm) | 2 | |
| 7 | 2907 | COLLAR | 1 | |
| 8 | 2908 | SCREW (SET 8mmx10mm) | 1 | |
| 9 | 2909 | COLLAR | 1 | |
| 10 | 2910 | FRAME | 1 | |
| 11 | 2903 | SCREW (CAP 8mmx55mm) | 2 | |
| 12 | 2902 | SWITCH AND COVER | 1 | |
| 13 | 2904 | SCREW (CAP 4mmx30mm) | 2 | |
| | | <u>CE COVER</u> | | |
| 1 | 2617 | END BRACKET | 1 | |
| 2 | 2605 | LEAD SCREW | 1 | |
| 3 | 2625 | ARM | 1 | |
| 4 | 2668 | PROTECTION HOOD | 2 | |
| 5 | 2626 | BUSH | 1 | |
| 6 | 2620 | ARM | 1 | |
| 7 | 2618 | COVER | 1 | |
| 8 | 2206 | SHAFT | 1 | |
| 9 | 2205 | COVER | 1 | |
| 10 | 2606 | SHAFT | 1 | |
| 11 | 2609 | COLLAR | 1 | |
| 12 | 2608 | COLLAR | 1 | |
| 13 | 2651 | SCREW (CAP 8mmx60mm) | 2 | |
| 14 | 2650 | PIN (5mmx50mm) | 2 | |
| 15 | 2649 | OIL CUP (1/4") | 3 | |
| 16 | 2658 | PLUG | 2 | |
| 17 | 2667 | THRUST (51104) | 1 | |
| 18 | 2666 | SCREW (SET 8mmx10mm) | 1 | |
| 19 | 2665 | STEEL BALL SPRING & SCREW | 2 | |
| 20 | 2664 | SCREW (SET 8mmx12mm) | 1 | |
| 21 | 2661 | SCREW (CAP 6mmx20mm) | 2 | |
| 22 | 2663 | SCREW (CAP 8mmx50mm) | 2 | |
| 23 | 2653 | PIN (5mmx50mm) | 2 | |
| 24 | 2662 | SCREW (CAP 8mmx16mm) | 1 | |
| 25 | 2263 | THRUST (51105) | 1 | |
| 26 | 2255 | SCREW (CAP 6mmx20mm) | 3 | |
| 27 | 2660 | SCREW (CAP 8mmx30mm) | 2 | |




CABINET AND PANELS, PUMP SYSTEM

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|-------------------------|------|---------|
| 1 | 2701 | LEFT PEDESTAL HEAD-END | 1 | |
| 2 | 2702 | RIGHT PEDESTAL TAIL-END | 1 | |
| 3 | 2704 | CHIP PAN | 1 | |
| 4 | 2705 | SPLASH GUARD | 1 | |
| 5 | 2709 | COVER | 1 | |
| 6 | 2708 | COVER | 1 | |
| 7 | 2707 | CHUTE | 1 | |
| 8 | 2703 | FOOT BRAKE PEDAL | 1 | |
| 9 | 2715 | CONNECTOR SHAFT | 1 | |
| 10 | 2716 | COLLAR | 1 | |
| 11 | 2714 | LEVER | 1 | |
| 12 | 2713 | LEVER | 1 | |
| 13 | 2712 | COLLAR | 1 | |
| 14 | 2711 | BAR | 1 | |
| 15 | 2745 | SPRING | 1 | |
| 16 | 2730 | WASHER | 1 | |
| 17 | 2719 | BAR | 2 | |
| 18 | 2718 | CONNECT PLATE | 1 | |
| 19 | 2710 | NUT | 2 | |
| 20 | 2732 | SCREW (1/2"x2") | 4 | |
| 21 | 2741 | SCREW (6mmx12mm) | 8 | |
| 22 | 2737 | SCREW (CAP 6mmx12mm) | 3 | |
| 23 | 2736 | SCREW (CAP 8mmx20mm) | 1 | |
| 24 | 2735 | SCREW (CAP 6mmx16mm) | 2 | |
| 25 | 2734 | SCREW (CAP 8mmx20mm) | 1 | |
| 26 | 2733 | SCREW (CAP 8mmx20mm) | 2 | |
| 27 | 2742 | SCREW (SET 10mmx20mm) | 2 | |
| 28 | 2743 | SCREW (SET 10mmx40mm) | 2 | |
| 29 | 2731 | SCREW (CAP 8mmx10mm) | 1 | |
| 30 | 2740 | SCREW (8mmx10mm) | 1 | |
| 31 | 2746 | NUT | 3 | |
| 32 | 2738 | SCREW (CAP 8mmx25mm) | 1 | |
| 33 | 2739 | SCREW (8mmx30mm) | 1 | |
| 34 | 2747 | SCREW (6mmx16mm) | 8 | |
| 35 | 2748 | NUT | 8 | |
| 36 | 2706 | TANK | 1 | |
| 37 | 2717 | PUMP (1/8 HP) | 1 | |
| 38 | 2720 | HOSE | 1 | |



SWING FRAME & GEARS, END COVER

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|-------------------------|------|---------|
| 1 | 2801 | SWING FRAM | 1 | |
| 2 | 2802 | BOLT | 1 | |
| 3 | 2803 | COLLAR | 1 | |
| 4 | 2804 | GEAR(M1.25x120T,127T) | 1 | |
| 5 | 2805 | SCREW | 1 | |
| 6 | 2808 | GEAR(1.25x60T) | 1 | |
| 7 | 2806 | COLLAR | 1 | |
| 8 | 2807 | GEAR(1.25x30T) | 1 | |
| 9 | 2821 | END COVER | 1 | |
| 10 | 2822 | STUD | 1 | |
| 11 | 2824 | STUD | 1 | |
| 12 | 2823 | NUT | 2 | |
| 13 | 2833 | BEARING(6202Z) | 2 | |
| 14 | 2836 | CIRCLIP(R 35) | 1 | |
| 15 | 2835 | NUT | 2 | |
| 16 | 2837 | WASHER | 1 | |
| 17 | 2839 | WASHER | 2 | |
| 18 | 2840 | SCREW(CAP 6mmx16mm) | 2 | |
| 19 | 2838 | NUT | 1 | |
| 20 | 2831 | WASHER | 1 | |
| 21 | 2830 | KEY (5mmx18mm) | 1 | |
| 22 | 2841 | KEY (5mmx18mm) | 1 | |
| 23 | 2827 | DATA PLATE | 1 | |
| 24 | 2817 | SCREW (3/16"x3/8") | 6 | |
| 25 | 2809 | CHANGE GEAR (M1.25x28T) | 1 | |
| 26 | 2810 | CHANGE GEAR (M1.25x35T) | 1 | |
| 27 | 2811 | CHANGE GEAR (M1.25x36T) | 1 | |
| 28 | 2812 | CHANGE GEAR (M1.25x49T) | 1 | |
| 29 | 2815 | CHANGE GEAR (M1.25x42T) | 1 | |
| 30 | 2813 | CHANGE GEAR (M1.25x38T) | 1 | |
| 31 | 2816 | CHANGE GEAR (M1.25x44T) | 1 | |
| 32 | 2818 | CHANGE GEAR (M1.25x52T) | 1 | |
| 33 | 2825 | CHANGE GEAR (M1.25x48T) | 1 | |
| 34 | 2826 | CHANGE GEAR (M1.25x56T) | 1 | |
| 35 | 2819 | CHANGE GEAR (M1.25x57T) | 1 | |
| 36 | 2820 | CHANGE GEAR (M1.25x65T) | 1 | |
| 37 | 2814 | CHANGE GEAR (M1.25x40T) | 1 | |



STEADY REST AND FOLLOW REST

| REF.NO. | PART NO. | DESCRIPTION | Q'TY | REMARKS |
|---------|----------|-------------|------|---------|
| 1 | 2917 | CASTING | 1 | |
| 2 | 2918 | CASTING | 1 | |
| 3 | 2919 | SHAFT | 5 | |
| 4 | 2920 | SCREW | 5 | |
| 5 | 2905 | COLLAR | 5 | |
| 6 | 2921 | HANDLE | 5 | |
| 7 | 2922 | SHAFT | 5 | |
| 8 | 2923 | SCREW | 1 | |
| 9 | 2924 | HANDLE | 1 | |
| 10 | 2925 | SHAFT | 1 | |
| 11 | 2926 | SCREW | 5 | |
| 12 | 2927 | SCREW | 5 | |
| 13 | 2928 | SPRING PIN | 5 | |
| 14 | 2929 | SPRING PIN | 1 | |
| 15 | 2915 | CASTING | 1 | |
| 16 | 2916 | SCREW | 2 | |

MACHINERYHOUSE

ELECTRIC EQUIPMENTS

CONSTRUCTION

THE ELECTRIC EQUIPMENTS ARE CONSISTS OF SPINDLE MOTOR, CONTROL PANEL, MAGNETIC CONTACTOR, MAGNETIC SWITCH, CONTROL CONDUIT AND TRANSFORMER.

- A. THE SPINDLE MOTOR IS TOTALLY ENCLOSED, 3 PHASES 3.7KW(5HP) 4 POLES.
- B. THE CONTROL PANEL INCLUDES POWER ON AND OFF SWITCHES, COOLANT PUMP SWITCH AND PILOT LAMP.
- C. THE MAGNETIC CONTROL PANEL HAS SPINDLE MOTOR, REVERSIBLE MAGNETIC VALVE. AND SUBSIDIARY MAGNETIC CONTACTOR.
- D. THE FORWARDING AND REVERSING RUNNING CONTROL LEVER IS CONTROLLED BY A MICRO SWITCH.
- E. A MICRO SWITCH FOR FOOT BRAKE PEDAL IS FITTED SEPARATELY. WHEN THE PEDAL IS USED, THE MAGNETIC SWITCH ON SPINDLE MOTOR WILL CUT OFF AUTOMATICALLY.

RUNNING STEPS

- 1. A POWER SWITCH IS FITTED ON THE CONTROL PANEL. PUT THIS SWITCH ON POSITION "ON" THEN THE PILOT LAMP IS LIGHTING.
- 2. PUSH OR PULL THE FORWARDING AND REVERSING RUNNING CONTROL LEVER THEN THE SPINDLE STARTS TO RUN.
- 3. UPON EMERGENCY STOP IS NEED, USE THE FOOT BRAKE PEDAL THEN THE SPINDLE MOTOR WILL CUT OFF AUTOMATICALLY. MEANWHILE, THE BRAKE IS ACTIVATED TO STOP RUNNING OF THE SPINDLE.
- 4. SUALLY, WHEN THE MACHINE NEEDS STOP, TO PUT ONLY THE LEVER CONTROL SWITCH ON THE MIDDLE POSITION. THUS, THE MAGNETIC SWITCH WILL CUT OFF AND THE MACHINE WILL SOP RUNNING.
- 5. UPON OPERATION IS COMPLETED, BE SURE TO PUT THE POWER SWITCH LOCATED AT THE CONTROL PANEL ON POSITION "OFF".

DISMOUNTING OF THE GAP BED

FIRST, TO TAKE OFF THE FOUR SCREWS MOUNTED ON THE SURFACE AND REMOVE THE PIN IN THE MIDDLE THEN MOVE THE GAP BED HORIZONTALLY AND GET IT DOWN. BE CAREFUL TO ITS PIN AND EDGES. KEEP THE GAP BED CAREFULLY AND DO NOT HIT IT. TO FOLLOW THE OPPOSITE STEPS FOR MOUNTING THE GAP BED BACK TO THE MACHINE. BEFORE MOUNTING, THE BED WAYS AD THE GAP HAVE TO BE CLEANED.

NOTES








1. BE SURE TO OPERATE ALWAYS THE MACHINE CAREFULLY AND KEEP IT WITH GOOD MAINTENANCE. IF SO, THE MACHINE'S LONGEVITY AND PRECISION CAN BE ASSURED.
2. EVERY DAY, WHEN THE OPERATION IS COMPLETED, BE SURE TO CLEAN OUT THE CHIPS LEAVE ON THE MACHINE AND OIL THE SLIDE WAYS TO PREVENT RUST AND MEANTIME, TURN OFF THE POWER SWITCH.
3. EVERY DAY, BEFORE OPERATION, BE SURE TO CHECK OIL LEVEL FOR OIL VOLUME AND FILL IT UP IF NECESSARY. ESPECIALYY, THE OIL SUPPLEMENT FOR FEED BOX IS EASILY FOGOTTEN BY THE OPERATOR. THE BEST WAY IS FEEDING OIL DAILY IN THE MORNING AND IN THE AFTERNOON SEPARATELY BEFORE RUNNING OF THE MACHINE.
4. FOR A NEW MACHINE, AFTER OPERATION OF 3 MONTHS, THE OIL IN HEAD-STOCK HAS TO BE REPLACED OR FILTERED IF IT TO BE USED REPEATEDLY. THUS, TO PROTECT THE GEARS INSIDE OF THE HEADSTOCK AND LESSEN THE NOISE.
5. IF HEADSTOCK IS OVER HEATED, HIGH WOBBLED, OIL LEAKED AND OIL SHORTED, THEN PLEASE STOP THE MACHINE IMMEDIATELY AND ARRANGE A PEOPLE TO SOLVE THE PROBLEM. WHEN THE PROBLEM IS SOLVED, THEN THE MACHINE CAN BE RUN AGAIN. OTHERWISE, MORE BIGGER PROBLEM IS COM-ING BECAUSE THE LITTLE CASE NOT CURED.
6. WHILE CLAMPING THE WORKPIECE, PLEASE DO NOT HIT IT BY HAMMER OR WEIGHT OTHERWISE THE SPINDLE WILL BE COLLIDED AND THE ACCURACY OF PRECISION IS EFFECTED.
7. AFTER OPERATION, THE HAND TOOLS, CUTTING TOOLS AND CLAMPING KITS SHOULD BE PUT ON APPROPRIATE POSITIONS. PLEASE DO NOT PUT ANY THING ON THE SLIDE WAYS OR BED WAY TO PREVENT COLLISION TO THE SLIDE WAYS AND EFFECT TO THE PRECISION.
8. BESIDES THE OPERATOR, PLEASE DO NOT LET ANYBODY ADJUST OR MOVE THE POSITION OF HANDLES OR CONTROLLING LEVERS, OR OPERATE THE MACHINE.
9. MAKE A TIME TABLE OF MACHINE MAINTENANCE AND MAINTAIN IT PERIODI-CALLY ACCORDING TO THE SCHEDULE, AND THUS TO BENEFIT THE PRECISION AND LONGEVITY OF THE MACHINE.









TROUBLE SHOOTING



| TROUBLES | FACTORS | REMEDY |
|---|--|--|
| HEADSTOCK BEARINGS ARE OVER HEATED | <ol style="list-style-type: none"> 1. OIL LEVEL IN HEADSTOCK IS TOO LOW. 2. OIL VISCOSITY IS WRONG. 3. OIL PIPE IS OBSTRUCTED OR LEAKED. 4. MAIN SPINDLE IS WOBBLED OR OVER LOADED. 5. OIL FILTER IS OBSTRUCTED. | <ol style="list-style-type: none"> 1. CHECK IF OIL LEVEL IN CORRECT POSITION AND FILL IT UP IF NECESSARY. 2. CHECK IF THE RECOMMENDED OIL IS USED. 3. CLEAN OIL PIPE OR REPLACE A NEW ONE IF NEED. 4. CHECK IF THE SPINDLE IS LOCKED UPON FREE RUNNING. 5. FILTER THE OIL OR REPLACE NEW OIL. |
| OIL LEAKAGE ON SPINDLE FLANGE OR GEAR BOX COVER | <ol style="list-style-type: none"> 1. BOLT IS LOOSE. 2. OIL PACKING IS WORN. 3. OIL VOLUME IS OVER. 4. OIL SEAL IS CRACKED. 5. THE SURFACE FINISH IS COARSE. | <ol style="list-style-type: none"> 1. LOCK THE BOLT. 2. REPLACE THE PACKING. 3. LOWER THE OIL. 4. REPLACE OIL SEAL. 5. CORRECT THE FINISH. |
| CHATTER | <ol style="list-style-type: none"> 1. WORKPIECE IS NOT CLAMPED SECURELY. 2. WORKPIECE LEAVES TOO LONG AT LEFT SIDE OF THE CLAMPING POSITION. 3. IMPROPER CUTTING TOOL IS USED. 4. CUTTING TOOL IS TOO HIGH OR TOO LOW TO THE CENTER OF SPINDLE. 5. CHIP IS NOT REMOVED FREELY FROM THE TOOL. 6. WORKPIECE IS TOO LONG. | <ol style="list-style-type: none"> 1. CLAMP IT SECURELY. 2. LESSEN THE LENGTH TO AVOID WOBBLE HAPPENED. 3. SELECT SUITABLE CUTTING TOOL ACCORDING TO MATERIAL OF WORKPIECE AND THE CUTTING SPEED. FOR SMALL DIAMETER OF WORKPIECE, A SMALL ANGLE OF CUTTING TOOL TO BE USED. IF OPPOSITE, USE THE BIG ANGLE OF CUTTING TOOL. 4. ADJUST THE CUTTING TOOL TO THE CENTER OF SPINDLE. 5. MOUNT A CHIP CUTTER OR ADJUST THE FRONT ANGLE OF CUTTING TOOL. 6. USE A CENTER TO SUPPORT LONGER WORKPIECE. |
| BENT FINISH ON LONG WORKPIECE CUTTING | <ol style="list-style-type: none"> 1. MATERIAL IS OVER HEATED. 2. DEEP CUT IS MADE. 3. HOT IS HAPPENED TO THE CENTER AND WORKPIECE. | <ol style="list-style-type: none"> 1. USE COOLANT OIL FOR CUTTING. 2. REDUCE THE DEPTH FOR EACH CUTTING. 3. USE ROLLING CENTER FOR HIGH SPEED RUNNING. |
| PRECISION IS GETTING WORSE | <ol style="list-style-type: none"> 1. WORKPIECE IS NOT BALANCE CLAMPED. 2. ALWAYS HIT THE WORKPIECE BY HAMMER. 3. CENTER OF SPINDLE IS NOT ALIGNMENT WITH THE CENTER OF TAILSTOCK. 4. MACHINE IS OUT OF THE HORIZONTAL. | <ol style="list-style-type: none"> 1. CLAMP WORKPIECE IN BALANCE 2. DO NOT HIT IT BY HAMMER. 3. ADJUST THE TAILSTOCK TO ALIGNMENT WITH THE CENTER OF SPINDLE. 4. CHECK PERIODICALLY HORIZONTAL OF MACHINE. |
| LEVER SWITCH IS HARD OPERATED | THE OPERATOR IS NOT FAMILIAR WITH OPERATION OF THE MACHINE. | THE LEVER SWITCH IS FITTED WITH A SAFETY DEVICE. DURING OPERATION, THE LEVER MUST BE MOVED SLIGHTLY TO RIGHT THEN OPERATE UPWARD OR DOWNWARD FOR RUNNING THE SPINDLE CLOCKWISE AND ANTICLOCKWISE. |

TOLERANCE PERMISSIBLE DIAGRAM




1.ACCURACY TEST.(mm)

| NO. | INSPECTION ITEM | | DIAGRAM | TOLERANCE PERMISSIBLE |
|-----|---|---|--|-----------------------|
| 1 | Straightness of bed slideway | a.Longitudinal direction (In vertical plane) |  | 0.04 |
| | | b.Transverse direction (In vertical plane) |  | 0.04 |
| 2 | Parallelism of bed slideways. | |  | 0.02 |
| 3 | Spindle nose runout | |  | 0.01 |
| 4 | Spindle taper hole runout | a.Nearest spindle nose |  | 0.01 |
| | | b.At a distance of 300mm | | 0.02 |
| 5 | Parallelism of center line of main spindle to longitudinal motion of carriage | a.In vertical plane |  | 0.025 |
| | | b.In horizontal plane | | 0.025 |
| 6 | Movement of compound slide parallel with main spindle in vertical plane (Hand feed) | |  | 0.01/150 |

| NO. | INSPECTION ITEM | | DIAGRAM | TOLERANCE PERMISSIBLE |
|-----|--|--|--|-----------------------|
| 7 | Main spindle for axial slip. measured at 2 points, displaced by 180° | |  | 0.015 |
| 8 | True running of center point of main spindle. | |  | 0.015 |
| 9 | Parallelism of tailstock spindle with bed ways. | a.In vertical plane (Front end rising) |  | 0.015/100 |
| | | b.In horizontal plane (Front end inclined to wards the direction of tool pressure. | | 0.015/100 |
| 10 | Parallelism of bed ways with center line of tailstock spindle hole. | a.In vertical plane (Free end of mandrel rising) |  | 0.02/300 |
| | | b.In horizontal plane (Free end of mandrel inclined to wards tailstock end) | | 0.02/300 |
| 11 | Difference in center height between headstock and tailstock (Mandrel rising towards tailstock end) | |  | 0.025 |
| 12 | Squareness of motion of cross slide with center line of main spindle | |  | 0.02/300 |
| 13 | Parallelism of center line of lead screw end bearing to carriage slide ways | a.In vertical plane |  | 0.1 |
| | | b.In horizontal plane | | 0.1 |
| 14 | Diviations in alignment of center line of lead screw end bearing with center line of half nut. | a.In vertical plane |  | 0.15 |
| | | b.In horizontal plane | | 0.15 |

| NO. | INSPECTION | DIAGRAM | TOLERANCE PERMISSIBLE |
|-----|---|--|-----------------------|
| 15 | Axial displacement of lead screw by turning |  | 0.01 |
| 16 | Pitch error of lead screw |  | 0.03/300 |

2. PRACTICAL

| NO. | TESTING ITEM | DIAGRAM | TOLERANCE PERMISSIBLE |
|-----|---------------------------------|--|-----------------------|
| 1 | Accuracy of outside turning |  | 0.01 |
| 2 | Accuracy of cylindrical turning |  | 0.025 |
| 3 | Accuracy of face turning |  | 0.02 |

3. CHECK OF MOTOR SPECIFICATION

| ITEM | HP | Ph | V | Hz | R.P.M. |
|--------|--------|--------|---|----------|--------------|
| Rating | 2 3 | 1 3 | | 50 60 | 1420 1700 |
| Actual | | | | | |



**THE DRAWINGS SHOWN HEREIN ARE
ONLY FOR REFERENCE. A CHANGE
OR AN IMPROVEMENT MADE ON THE
MACHINE FOR BEST PERFORMANCE
IS UNAVOIDABLE.
IF ANY DIFFERENCE AMONG THEM
PLEASE FOLLOW THE SPECIFICATIONS
ON THE MACHINE.**