


Dear Customer

Thank for Your purchase of the Cosen NC Bandsaw.

Please Note that when cutting materials smaller than 65mm to 20mm you will need to remove the first vice plate



For parts smaller then 20mm you must also remove the second plate

Failure to remove the plates will cause damage to the blade guard and is not covered by warranty.