






APPLICATION OF CHANGE GEARS


- REMARKS:
- A: gear to be hanged on spindle arbor
 - B: moving wheel (I)
 - C: moving wheel(II)
 - D: gear rotation of gear case arbor
 - E: gear(I) to be hanged on bracket
 - F: gear(II) to be hanged on bracket
 - G: gear case arbor
 - H: holes of dividing plate
 - N: rotation of crank handle
 - R_L: bracket
 - S: spindle arbor




FIG(A)



FIG(B)



FIG(C)



FIG(D)

[illegible]

[illegible]

[illegible]