

# WLL 1000 KG MOBILE Girder Rail


## Extra Customer instructions to be used in conjunction with Factory assembly drawing

Please follow positioning and orientation of parts as per factory Assembly drawing supplied, using details below as reference.

When putting nuts and bolts together on Lifting equipment, it is a good practice to put bolt up from underneath and nut on top.

This way if nut comes loose, bolt falls out and it will be noticed missing .

If put with bolt from top and the nut falls off, the bolt stays were it is and is not noticed as a problem as readily.




Note position of lifting hooks assembled on inside edges of "U" lifting lever

N.B. Only ONE Lifting/Safety Pin is shown in these pictures for instruction picture clarity...Two Pins Must always be left in, and Lynch Pins must always be fitted when not adjusting height of trolley.

# Never use only one PIN to try and exceed limits of use.



Lynch Pin fitted correctly



2 Pins fitted ALL the time