




Wire 7 on pin 1 wire 13 on pin 3 keep switch front facing you!



Left 3-1 have jumper, metal jumper 3 to 4 keep switch front facing you!



Wire 5 on pin 4 and wire 4 on pin 2 Note 4&2 are bridged

keep switch front facing you!

LF1000 Forward & Reverse Switch

Lathe wire number **Switch Terminal Number**



If lathe operates the wrong way reverse wires numbers 7 and 13