


Hypertherm®

MAXPRO200®




MAXPRO200 machine torch consumables

Air – Mild steel/Stainless steel/Aluminum




	Shield	Shield cap	Nozzle	Swirl ring	Electrode	Water tube
50 A	220532	220936	220890	220529	220528	220521
130 A	220536	220936	220892	220488	220487	220521
200 A	420045	220936	420044	220488	220937	220521

O₂ – Mild steel



	Shield	Shield cap	Nozzle	Swirl ring	Electrode	Water tube
50 A	220532	220936	220891	220529	220528	220521
130 A	220491	220936	220893	220488	220487	220521
200 A	220832	220936	220831	220834	220937	220521

N₂ – Stainless steel/Aluminum



	Shield	Shield cap	Nozzle	Swirl ring	Electrode	Water tube
130 A	220536	220936	220892	220529	020415	220521
200 A	420045	220936	420044	220529	020415	220521



MAXPRO200 quick-disconnect machine torch



MAXPRO200 straight machine torch